# CARFAX Report

US $44.99

**VIN:** WDB1240921F312194

1 Detailed Record Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/21/26 at 10:12:31 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## CARFAX Additional History

Not all accidents / issues are reported to CARFAX

| | Summary |
|---|---|
| **Total Loss**<br>No total loss reported to CARFAX. | No Issues Reported |
| **Structural Damage**<br>No structural damage reported to CARFAX. | No Issues Reported |
| **Airbag Deployment**<br>No airbag deployment reported to CARFAX. | No Issues Reported |
| **Odometer Check**<br>No indication of an odometer rollback. | No Issues Indicated |
| **Accident / Damage**<br>No accidents or damage reported to CARFAX. | No Issues Reported |
| **Manufacturer Recall**<br>Check with an authorized dealer for any open recalls. | **Ask Your Dealer** |
| **Basic Warranty**<br>No data reported to CARFAX. | No Data Reported |

## CARFAX Title History

| | Summary |
|---|---|
| **Damage Brands**<br>Salvage \| Junk \| Rebuilt \| Fire \| Flood \| Hail \| Lemon | No Problem |
| **Odometer Brands**<br>Not Actual Mileage \| Exceeds Mechanical Limits | No Problem |

## CARFAX Detailed History

| Date | Mileage | Source | Comments |
|---|---|---|---|

| | | |
|---|---|---|
| 10/12/2023 | Florida<br>Motor Vehicle Dept.<br>Boca Raton, FL<br>Title #0152414782 | **Title issued or updated**<br>Dealer took title of this vehicle while it was in inventory<br>Exempt from odometer reporting<br>Vehicle color noted as Silver |

Hmm, we haven't received any information on this car since October 2023. Before you buy, ask the seller for recent service or repair records.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

## CARFAX Glossary

**Title Issued**
A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

**Follow Us:** facebook.com/CARFAX @CARFAXinc About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
5/21/26 10:12:31 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 0 null null vehicle (VIN: WDB1240921F312194), which is based on information supplied to CARFAX and available as of 5/21/26 at 11:12 AM (EDT).**

**Customer Signature** **Date** **Dealer Signature** **Date**

# Vehicle History Report

## VEHICLE DETAILS

| | |
|---|---|
| **Chassis number [1]:** | WDB1240921F312194 |
| **Manufacture date:** | 1995 |
| **Make:** | MERCEDES BENZ |
| **Model:** | E CLASS |
| **Body:** | |
| **Grade:** | E36 AMG ESTATE |
| **Engine:** | 104992 |
| **Drive:** | 2WD |
| **Transmission:** | AT |

| | | |
|---|---|---|
| **Title information [2]:** | **Deregistered to Export** | ✓ |
| **Accident / Repair:** | **Problem found** | ✗ |
| **Odometer rollback:** | **Problem found** | ✗ |
| **Manufacturer recall:** | **No problem** | ✓ |
| **Safety grade [3]:** | **No data** | ✓ |
| **Contamination risk:** | **No problem** | ✓ |

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2026-06-06 19:28:11. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## ACCIDENT / REPAIR HISTORY

| Problem type | Reported | Date reported | Data source | Details | Airbag |
|---|---|---|---|---|---|
| Collision | Reported | | | | |
| — | — | 2018-05-15 | USS Yokohama | Repaired | OK |
| Malfunction | Not reported | | | | |
| Theft | Not reported | | | | |
| Fire damage | Not reported | | | | |
| Water damage | Not reported | | | | |
| Hail damage | Not reported | | | | |

## ODOMETER READINGS HISTORY

| Date reported | Data source | Odometer reading (Km) |
|---|---|---|
| 2014-06-03 | MLIT | 297900 |
| 2016-05-27 | MLIT | 326000 |
| 2018-05-15 | USS Yokohama | 12283 |

## USE HISTORY

| Use in the contaminated regions [4] | Radioactive contamination test fail [5] | Commercial use |
|---|---|---|
| Not reported | Not reported | Not reported |

## DETAILED HISTORY

| Event date | Location | Odometer reading (Km) | Data source | Details |
|---|---|---|---|---|
| 1995 | | | MERCEDES BENZ | Manufactured |
| 1995-05 | | | MLIT | First registration |
| 2014-06-03 | | 297900 | MLIT | Inspection |
| 2016-05-27 | Yokohama | 326000 | MLIT | Inspection |

| | | | | |
|---|---|---|---|---|
| 2018-03-30 | Yokohama | | MLIT | Last registration |
| 2018-05-15 | Kanagawa | 12283 | USS Yokohama | Auctioned |

## MANUFACTURER RECALL HISTORY

| Date reported | Data source | Affected part | Details |
|---|---|---|---|
| Not reported | | | |

## VEHICLE ASSESSMENT [6]

**Overall Collision Safety Ratings**

| Driver's seat | | | Front passenger's seat | | |
|---|---|---|---|---|---|
| Points | Evaluation | Goal average | Points | Evaluation | Goal average |
| 0 | | 0% | 0 | | 0% |

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

**Braking performance tests** [7]

Dry road

Wet road

## VEHICLE SPECIFICATION

| | | |
|---|---|---|
| **1st gear ratio** | **2nd gear ratio** | |
| **3rd gear ratio** | **4th gear ratio** | |
| **5th gear ratio** | **6th gear ratio** | |
| **Additional notes** | **Airbag position, capacity** | |
| **Body rear overhang** | **Body type** | STATION WAGON |

| | | | |
|---|---|---|---|
| **Chassis number embossing position** | | **Classification code** | |
| **Cylinders** | | **Displacement** | 3600 |
| **Electric engine type** | | **Electric engine maximum output** | |
| **Electric engine maximum torque** | | **Electric engine power** | |
| **Engine maximum power** | 271ps(----kW)/5500rpm | **Engine maximum torque** | 43.3kg· m(----N· m)/3750rpm |
| **Engine model** | 104992 | **Frame type** | |
| **Front shaft weight** | 890 | **Front shock absorber type** | |
| **Front stabilizer type** | | **Front tires size** | 225/45ZR17 |
| **Front tread** | 1505 | **Fuel consumption** | |
| **Fuel tank equipment** | 72 | **Grade** | E36 AMG ESTATE |
| **Height** | 146 | **Length** | 478 |
| **Main brakes type** | | **Make** | MERCEDES BENZ |
| **Maximum speed** | | **Minimum ground clearance** | |
| **Minimum turning radius** | 5.2m | **Model** | E CLASS |
| **Model code** | | **Mufflers number** | |
| **Rear shaft weight** | 830 | **Rear shock absorber type** | |
| **Rear stabilizer type** | | **Rear tires size** | 225/45ZR17 |
| **Rear tread** | 1510 | **Reverse ratio** | |
| **Riding capacity** | 7 | **Side brakes type** | |
| **Specification code** | | **Stopping distance** | |
| **Transmission type** | AT | **Weight** | 1720 |
| **Wheel alignment** | 2WD | **Wheelbase** | 2800 |
| **Width** | 177 | | |

## AUCTION DATA

**Date: 2018-05-15, Auction: USS Yokohama, Lot #: 86157**

| | | | |
|---|---|---|---|
| Date: | 2018-05-15 | Lot #: | 86157 |
| Auction name: | USS Yokohama | Region: | Kanagawa |
| Make: | MERCEDES BENZ | Model: | E CLASS |
| Reg. year: | 1995 | Mileage (km): | 12283 |
| Displacement (cc): | 3600 | Transmission: | FAT |
| Color: | SILVER | Model code: | |
| Result: | available | Auction grade: | R |
| Problem type: | Collision | Problem scale: | Repaired |
| Contaminated: | No | Airbag: | OK |

## PHOTOS AND AUCTION SHEETS



## GLOSSARY

[1] **Chassis number** – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

[2] **Title information:**
Registered – qualified for driving in Japan
Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change
Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped
Deregistered to Export – not qualified for driving in Japan , the vehicle is determined to be exported

[3] **Determining the overall collision safety performance evaluation** – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

[4] **Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

[5] **Radioactive contamination test** – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

[6] **Japan New Car Assessment Program** – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test , rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

[7] **Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION.

THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2026 Car VX Limited. All rights reserved.

# Zulassungsbescheinigung Teil I
(Fahrzeugschein)

Nr. AA-K-0-251/20-00089

Europäische Gemeinschaft (D) Bundesrepublik Deutschland

Свидетелство за регистрация - Част I / Permiso de circulación. Parte I / Osvědčení o registraci - Část I /Registreringsattest. Del I / Registreerimistunnistus. Osa I / Άδεια κυκλοφορίας/Πιστοποιητικό Εγγραφής. Μέρος I / Registration certificate. Part I / Certificat d'immatriculation. Partie I / Prometna dozvola I / Carta di circolazione. Parte I / Reģistrācijas apliecība. I. daļa / Registracijos liudijimas. I dalis / Forgalmi engedély. I. Rész / Certifikat ta' Reġistrazzjoni. L-I Parti / Kentekenbewijs. Deel I / Dowód Rejestracyjny. Część I / Certificado de matrícula. Parte I / Certificat de înmatriculare Partea I / Osvedčenie o evidencii. Časť I / Prometno dovoljenje. Del I / Rekisteröintitodistus. Osa I / Registreringsbeviset. Del I

A Amtliches Kennzeichen: AA KY635

C.1.1 Name oder Firmenname: AUTOHAUS RÖMER OHG

C.1.2 Vorname(n):

C.1.3 Anschrift:
KARLSTR. 2 /1
73433 AALEN

AALEN

X Nächste HU (Monat und Jahr): 09.2022 I Datum: 07.09.2020

C.4c Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des Fahrzeugs ausgewiesen.

| | | | | | |
|---|---|---|---|---|---|
| B | 30.05.1995 | 2.1 | 0708 | 2.2 | 00000000-01 |
| J | | 4 | 0200 | | |
| E | WDB1240921F312194 | 3 | 6 | | |
| D.1 | MERCEDES-BENZ | | | | |
| D.2 | 124 T<br>-<br>- | | | | |
| D.3 | E36 AMG | | | | |
| 2 | DAIMLER-BENZ (D) | | | | |
| 5 | PERSONENKRAFTWAGEN<br>GESCHLOSSEN | | | | |
| V.9 | - | | | | |
| 14 | SCHADSTOFFARM E2 | | | | |
| P.3 | BENZIN | | | | |
| 10 | 0001 | 14.1 | 0414 | P.1 | 03606 |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| L | 02 | 9 | 01 | P.2 P.4 | 0200/05750 | T | 236 |
| 18 | 04765 -- | | | 19 | 1740-- | | |
| 20 | 1428 - - | | | G | 001690-- | | |
| 12 | - | 13 | - | Q | - | | |
| V.7 | - | F.1 | 002200 | F.2 | 002200 | | |
| 7.1 | 01000 | 7.2 | 01200 | 7.3 | - | | |
| 8.1 | 01000 | 8.2 | 01200 | 8.3 | - | | |
| U.1 | 83P | U.2 | 04000 | U.3 | 74 | | |
| O.1 | - | O.2 | - | S.1 | 005 | S.2 | - |
| 15.1 | 225/45R17 91W | | | | | | |
| 15.2 | 225/45R17 91W | | | | | | |
| 15.3 | - | | | | | | |
| R | | 11 | 7 | | | | |
| K | - | | | | | | |
| 6 | - | 17 | E | 16 | FW486478 | | |
| 21 | - | | | | | | |

22 ZU 15: A.AMG LM-RAD 7,5JX17H2 ET42 1244001302*ZU 15: A
.GEN. 205/60R15 91T M+S A.MERCEDES-BENZ RAD 7JX15H2 ET
41 A1244010902 WAHLW.A1244011302*M.AMG-MOTOR M104-3.6*
ACHSANTRIEB 3,0*AMG FAHRWERKSATZ (FEDERN UND ANGEP.STO
ßDÄMPFER)*AMG-GESCHWINDIGKEITSMESSER ANZEIGEBEREICH 28
0KM/H*M.AMG SEITENSCHWELLER W124 TYP: 007124881, FRONT
SPOILER W124 TYP: 001124881 FORTSETZUNG S. BEIBLATT

# Zulassungsbescheinigung Teil I

(Fahrzeugschein)

Nr. AA-K-0-251/20-00089

Europäische Gemeinschaft (D) Bundesrepublik Deutschland

Свидетелство за регистрация - Част I / Permiso de circulación. Parte I / Osvědčení o registraci - Část I /Registreringsattest. Del I / Registreerimistunnistus. Osa I / Άδεια κυκλοφορίας/Πιστοποιητικό Εγγραφής. Μέρος I / Registration certificate. Part I / Certificat d'immatriculation. Partie I / Prometna dozvola I / Carta di circolazione. Parte I / Reģistrācijas apliecība. daļa / Registracijos liudijimas. I dalis / Forgalmi engedély. I. Rész / Certifikat ta' Registrazzjoni. L-I Parti / Kentekenbewijs. Deel I / Dowód Rejestracyjny. część I / Certificado de matrícula. Parte I / Certificat de înmatriculare Partea I / Osvedčenie o evidencii. Časť I / Prometno dovoljenje. Del I / Registreringsbevis. Del I

Amtliches Kennzeichen:

**AA KY635**

.1.1 Name oder Firmenname

AUTOHAUS RÖMER OHG

.1.2 Vorname(n)

.1.3 Anschrift

KARLSTR. 2 /1
73433 AALEN

Nächste HU (Monat und Jahr): AALEN

09.2022 Datum: 07.09.2020

4c Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des Fahrzeugs ausgewiesen.

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| B | 30.05.1995 | 2.1 | 0708 | 2.2 | 00000000- | L | 02 | 9 | 01 | P.2 P.4 | 0200/05750 | T | 236 |
| J | 01 | 4 | 0200 | | | 18 | 04765 -- | 19 | 1740-- | | | | |
| E | WDB1240921F312194 | 3 | 6 | | | 20 | 1428 - - | G | 001690-- | | | | |
| D.1 | MERCEDES-BENZ | | | | | 12 | - | 13 | - | Q | - | | |
| D.2 | 124 T | | | | | V.7 | - | F.1 | 002200 | F.2 | 002200 | | |
| | - | | | | | 7.1 | 01000 | 7.2 | 01200 | 7.3 | - | | |
| | - | | | | | 8.1 | 01000 | 8.2 | 01200 | 8.3 | - | | |
| | | | | | | U.1 | 83P | U.2 | 04000 | U.3 | 74 | | |
| D.3 | E36 AMG | | | | | O.1 | - | O.2 | - | S.1 | 005 | S.2 | - |
| 2 | DAIMLER-BENZ (D) | | | | | 15.1 | 225/45R17 91W | | | | | | |
| 5 | PERSONENKRAFTWAGEN | | | | | 15.2 | 225/45R17 91W | | | | | | |
| | GESCHLOSSEN | | | | | 15.3 | - | | | | | | |
| V.9 | - | | | | | R | | 11 | 7 | | | | |
| 14 | SCHADSTOFFARM E2 | | | | | K | - | | | | | | |
| P.3 | BENZIN | | | | | 6 | - | 17 | E | 16 | FW486478 | | |
| 10 | 0001 | 14.1 | 0414 | P.1 | 03606 | 21 | - | | | | | | |

22 ZU 15: A.AMG LM-RAD 7,5JX17H2 ET42 1244001302*ZU 15: A .GEN. 205/60R15 91T M+S A.MERCEDES-BENZ RAD 7JX15H2 ET 41 A1244010902 WAHLW.A1244011302*M.AMG-MOTOR M104-3.6* ACHSANTRIEB 3,0*AMG FAHRWERKSATZ (FEDERN UND ANGEP.STO ßDÄMPFER)*AMG-GESCHWINDIGKEITSMESSER ANZEIGEBEREICH 28 0KM/H*M.AMG SEITENSCHWELLER W124 TYP: 007124881, FRONT SPOILER W124 TYP: 001124881 FORTSETZUNG S. BEIBLATT

,(FORTSETZUNG AUF BEIBLATT)HECKSCHÜRZE W124 TYP: 001124882* BASISFAHRZEUG MERCEDES-BENZ E320T***DATUM ZUR EMISSIONSKLASSE: 30.05.1995*

## Beiblatt zur Zulassungsbescheinigung Teil I

**AA KY635**

WDB1240921F312194

DAIMLER-BENZ (D)

Landratsamt
Ostalbkreis
Zulassungsbehörde
AALEN

RieCQ-Vordr. V24

# Europäische Gemeinschaft
# Bundesrepublik Deutschland
## Zulassungsbescheinigung Teil II
(Fahrzeugbrief)

D

Свидетелството за регистрация - Част II / Permiso de circulación. Parte II / Osvědčení o registraci – Část II / Registreringsattest. Del II / Registreerimistunnistus. Osa II / Άδεια κυκλοφορίας/Πιστοποιητικό Εγγραφής. Μέρος II / Registration certificate. Part II / Certificat d'immatriculation. Partie II / Prometna dozvola II / Carta di circolazione. Parte II / Registrācijas apliecība. II. daļa / Registracijos liudijimas. II dalis / Forgalmi engedély. II. Rész / Certifikat ta' Registrazzjoni. It-II Parti / Kentekenbewijs. Deel II / Dowód Rejestracyjny. Część II / Certificado de matrícula. Parte II / Certificat de Immatriculare Partea II / Osvědčenie o evidencii. Časť II / Prometno dovoljenje. Del II / Rekisterointitodistus. Osa II / Registreringsbeviset. Del II

**Diese Bescheinigung nicht im Fahrzeug aufbewahren!**

| | | | |
|---|---|---|---|
| A | Amtliches Kennzeichen | AA KY635 | |
| B | Datum der Erstzulassung des Fahrzeugs | 30.05.1995 (1) Anzahl der Vorhalter – | (1) Anzahl der Vorhalter |
| C.3.1 C.6.1 | Name oder Firmenname | AUTOHAUS RÖMER OHG | |
| C.3.2 C.6.2 | Vorname(n) | | |
| C.3.3 C.6.3 | Anschrift zum Zeitpunkt der Ausstellung der Bescheinigung | KARLSTR. 2 /1<br>73433 AALEN | |
| C.4c | | Der Inhaber der Zulassungsbescheinigung wird nicht als Eigentümer des Fahrzeugs ausgewiesen. | |
| I | Datum | 07.09.2020 | I Datum |

FyL49IHw80

BADEN-WÜRTTEMBERG D049663 LANDRATSAMT OSTALBKREIS

LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE
AALEN

Nur zur Nutzung des Sicherheitscodes im internetbasierten Zulassungsverfahren freilegen. Dokument nur unbeschädigt gültig.

FW486478

(Nummer der Zulassungsbescheinigung)

(Fahrzeug-Identifizierungsnummer als Barcode)

| | | | |
|---|---|---|---|
| D.1 | Marke | MERCEDES-BENZ | |
| D.2 | Typ | 124 T | |
| | Variante | – | |
| | Version | – | |
| D.3 | Handelsbezeichnung(en) | E36 AMG | |
| (2) | Hersteller-Kurzbezeichnung | DAIMLER-BENZ (D) | |
| (2.1) | Code zu (2) | 0708 (2.2) Code zu D.2 mit Abschnitt | 000 00000- |
| E | Fahrzeug-Identifizierungsnummer | WDB1240921F312194 (3) Prüfziffer zur Fahrzeug-Identifizierungsnr. | 6 |
| J | Fahrzeugklasse | 01 (4) | 0200 |
| (5) | Bezeichnung der Fahrzeugklasse und des Aufbaus | PERSONENKRAFTWAGEN<br>GESCHLOSSEN | |
| R | Farbe des Fahrzeugs | (11) Code zu R | 7 |
| P.1 | Hubraum in cm³ | 03606 P.2 P.3 Zulassungsfähige Leistung in kW | 0200/05750 |
| P.3 | Kraftstoffart oder Energiequelle | BENZIN (10) Code zu P.3 | 0001 |
| K | Nummer der EG-Typgenehmigung oder ABE | – (6) Datum | – |
| (17) | Merkmal zur Betriebserlaubnis | E | |

(23) Raum für interne Vermerke des Herstellers

(24) Diese Bescheinigung wurde für das nebenstehend beschriebene Fahrzeug ausgegeben durch Zulassungsbehörde bzw. Genehmigungsinhaber:

LANDRATSAMT
OSTALBKREIS
KFZ-ZULASSUNGSBEHÖRDE

Datum: 07.09.20

Unterschrift: Eberhard

(25) Zusätzliche Vermerke der Zulassungsbehörde:

BISH. ZULASSUNGSBESCH. TEIL II / BISH. FAHRZEUGBRIEF
U ENTWERTET UND ZURÜCKGEGEBEN

NR.: FW486573

**Leading Edge Autosport**
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

**INVOICE**

**5006**

Org. Est. # 005445

Tax Resale # : 7124467

# INVOICE

Work Completed : 01/11/2021

**Date: 02/08/2021**

1995 Mercedes-Benz - e36 - 3.2l inline six

Lic # : 312194

Odometer In : 12491

VIN # : WDB124092 **1F312194**

| Part Description / *Number* | Qty | Sale | Ext |
|---|---|---|---|
| left boot<br>*124-811-01* | 1.00 | 145.35 | 145.35 |
| right boot<br>*124-811-04* | 1.00 | 243.53 | 243.53 |
| gasket<br>*126-271-11* | 1.00 | 9.78 | 9.78 |
| ATF Dextron 3<br>*DexIII* | 6.00 | 4.25 | 25.50 |
| trans filter<br>*126-277-02* | 1.00 | 29.96 | 29.96 |
| Wiper Blade<br>*26CA* | 1.00 | 15.95 | 15.95 |
| bulb<br>*9003* | 2.00 | 9.38 | 18.76 |
| rear cover<br>*cover* | 2.00 | 77.78 | 155.56 |
| 5w40 Synthetic<br>*5w40* | 8.00 | 7.55 | 60.40 |
| oil filter<br>*104-180-01* | 1.00 | 12.44 | 12.44 |
| Brake Fluid - L<br>*DOT4* | 3.00 | 12.99 | 38.97 |
| Brake Hose<br>*171 428 00 35* | 2.00 | 18.32 | 36.64 |
| Brake Hose<br>*204 428 04 35* | 2.00 | 22.08 | 44.16 |
| shipping calipers for rebuild<br>*shipping* | 1.00 | 25.00 | 25.00 |
| Brake Pad Set w/ Shims<br>*005 420 17 20-41* | 1.00 | 56.98 | 56.98 |
| Brake Disc<br>*124 423 10 12* | 2.00 | 87.08 | 174.16 |
| Brake Pad Sensor<br>*140 540 12 17* | 2.00 | 4.94 | 9.88 |
| Drive Belt<br>*6PK-2475* | 1.00 | 49.42 | 49.42 |
| pa tire tax<br>*tire tax* | 4.00 | 1.00 | 4.00 |
| kumho ecsta<br>*225/45r17* | 4.00 | 99.95 | 399.80 |
| air filter<br>*air filter* | 1.00 | 57.38 | 57.38 |

| Labor Description | Hours | Ext |
|---|---|---|
| rear brake feel like they are hanging up<br>rear tires dry rot bad<br>vibration in rear of vehicle | | |
| Safety Check / Multi-Point Inspection<br>Brakes- F: 5 R: 4<br>Tires- F: 9 R: 5<br>SI Due- na | 0.39 | 44.95 |
| replace both mirror boots | 1.50 | 185.93 |
| perform transmission service, change filter, gasket, and fluid | 1.50 | 185.93 |
| replace both headlight wiper blades | 0.80 | 99.16 |
| install right headlight rear cover, replace both headlight bulbs | 1.00 | 123.95 |
| Lube Oil & Filter Change | 0.21 | 24.95 |
| replace all 4 brake hoses and flush system | 3.00 | 371.85 |
| replace rear bake calipers, pads, and rotors | 2.50 | 309.88 |
| rebuild both rear calipers with shipping back | | 525.00 |
| replace drive belt | 0.70 | 86.77 |
| Mount & Balance 4 Tires<br>Dealer Rate | 1.26 | 145.00 |
| replace air filter | 0.30 | 37.19 |
| replace valve cover gasket | 4.50 | 557.78 |
| sand blast valve cover and center section when removed, prime, and repaint factory silver | 1.50 | 185.93 |
| replace rear pinion seal and nut | 2.00 | 247.90 |
| replace oil pressure switch | 1.20 | 148.74 |
| ALIGNMENT<br>***Break Tie Rods Loose For Alignment*** | | 169.00 |

Visit us on the web: www.Leadingedgeautosport.com

Email Address: ***Leadingedgeautosport@gmail.com***



Copyright (c) 2021 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

**Leading Edge Autosport**
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

**INVOICE**

**5006**

Org. Est. # 005445

# INVOICE

Tax Resale # : 7124467

Work Completed : 01/11/2021

**Date: 02/08/2021**

1995 Mercedes-Benz - e36 - 3.2l inline six

Lic # : 312194

Odometer In : 12491

VIN # : WDB124092 **1F312194**

| Part Description / *Number* | Qty | Sale | Ext | Labor Description | Hours | Ext |
|---|---|---|---|---|---|---|
| valve cover gasket kit<br>*gasket kit* | 1.00 | 89.38 | 89.38 | | | |
| high temp primer, paint, and clear coat for valve cover<br>*paint* | 1.00 | 25.99 | 25.99 | | | |
| pinion washer<br>*washer* | 1.00 | 8.68 | 8.68 | | | |
| pinion nut<br>*pinion nut* | 1.00 | 12.24 | 12.24 | | | |
| Gear Oil GL5<br>*75W90* | 2.00 | 19.95 | 39.90 | | | |
| rear pinion seal<br>*pinion seal* | 1.00 | 44.88 | 44.88 | | | |
| oil pressure switch<br>*oil pressure* | 1.00 | 129.19 | 129.19 | | | |
| invoice past due one month 20% fee added<br>*failure to pay* | 1.00 | 582.76 | 582.76 | | | |

[ Payments - Check - $2,500.00 ]

***Share Your Experience! Leave Us A Review On Facebook!***

I hereby authorized the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work must be performed in our shop & cannot exceed the original cost of repair. Any vehicle left on premises for any amount of time exceeding fourteen (14) days after work is completed will be subject to a $75/ day storage fee. Any parts - new, used, or otherwise - left on premises for any amount of time exceeding thirty (30) days after work is completed will become property of Leading Edge Autosport LLC.
NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

| | |
|---|---|
| Labor: | 2,755.91 |
| Parts: | 2,546.64 |
| Sublet: | 694.00 |
| Sub: | 5,996.55 |
| Tax: | 0.00 |
| Total: | $5,996.55 |
| Bal Due: | $3,496.55 |

***Share Your Experience! Leave Us A Review On Facebook!***

Vehicle Received: 11/22/2020

Customer Number : 1651

Signature _____ Date _____

Visit us on the web: www.Leadingedgeautosport.com

Email Address: ***Leadingedgeautosport@gmail.com***



Copyright (c) 2021 Mitchell Repair Information Company, LLC invhrs 1.16.20dc

**Leading Edge Autosport**
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

REPAIR ORDER #
005006
Org. Est. # 005445

# REPAIR ORDER - RO

Scheduled : 11/22/2020 04:09 PM

Print Date : 11/30/2020

2001 Mercedes-Benz - e36 - gas
Lic # : 312194 - PA

VIN # : WDB124092 **1F312194**
MFG Date : 11/22/2020
Current Odom : 12491

[redacted]

Elapsed : 0

| Labor Requested / Part Description | Part # | Qty | Parts List | Extended |
|---|---|---|---|---|
| *rear brake feel like they are hanging up*<br>*rear tires dry rot bad*<br>*vibration in rear of vehicle*<br>*Safety Check / Multi-Point Inspection* | | | | *44.95* |
| *Brakes- F: 5 R: 4*<br>*Tires- F: 9 R: 5*<br>*SI Due- na* | | | | |
| | | | | *185.93* |
| *replace both mirror boots* | | | | |
| left boot | 124-811-01 | 1.00 | 145.35 | 145.35 |
| right boot | 124-811-04 | 1.00 | 243.53 | 243.53 |
| | | | | *185.93* |
| *perform transmission service, change filter, gasket, and fluid* | | | | |
| gasket | 126-271-11 | 1.00 | 9.78 | 9.78 |
| ATF Dextron 3 | DexIII | 6.00 | 4.25 | 25.50 |
| trans filter | 126-277-02 | 1.00 | 29.96 | 29.96 |
| | | | | *99.16* |
| *replace both headlight wiper blades* | | | | |
| Wiper Blade | 26CA | 1.00 | 15.95 | 15.95 |
| | | | | *12.40* |
| *install right headlight rear cover* | | | | |
| rear cover | cover | 1.00 | 77.78 | 77.78 |
| | | | | *24.95* |
| *Lube Oil & Filter Change* | | | | |
| 5w40 Synthetic | 5w40 | 8.00 | 7.55 | 60.40 |
| oil filter | 104-180-01 | 1.00 | 12.44 | 12.44 |
| | | | | *371.85* |
| *replace all 4 brake hoses and flush system* | | | | |
| Brake Fluid - L | DOT4 | 3.00 | 12.99 | 38.97 |
| Brake Hose-Rear | 171 428 00 35 | 2.00 | 18.32 | 36.64 |
| Brake Hose-Front | 204 428 04 35 | 2.00 | 22.08 | 44.16 |
| | | | | *309.88* |
| *replace rear bake calipers, pads, and rotors* | | | | |
| Brake Disc-Rear | 210 423 05 12 64 | 2.00 | 63.32 | 126.64 |
| Brake Pad Set-Rear w/ Shims | 003 420 30 20 41 | 1.00 | 76.09 | 76.09 |
| Brake Caliper-Rear Left Unloaded w/o Bracket | 19-1861 | 1.00 | 94.63 | 94.63 |
| Brake Caliper-Rear Right Unloaded w/o Bracket | 19-1860 | 1.00 | 92.60 | 92.60 |
| | | | | *86.77* |
| *replace drive belt* | | | | |
| Drive Belt | 6PK-2475 | 1.00 | 49.42 | 49.42 |
| | | | | *145.00* |
| *Mount & Balance 4 Tires* | | | | |
| pa tire tax | tire tax | 4.00 | 1.00 | 4.00 |
| kumho ecsta | 225/45r17 | 4.00 | 99.95 | 399.80 |
| | | | | *37.19* |
| *replace air filter* | | | | |
| air filter | air filter | 1.00 | 57.38 | 57.38 |
| | | | | *557.78* |
| *replace valve cover gasket* | | | | |
| valve cover gasket kit | gasket kit | 1.00 | 89.38 | 89.38 |



Copyright (c) 2020 Mitchell Repair Information Company, LLC ropartdetail2 dj 7.2.16

**Leading Edge Autosport**
319 Westtown Rd Ste 1
West Chester, PA. 19382
Phone: 610-431-8459
Precision, Performance, Perfection

REPAIR ORDER #
005006
Org. Est. # 005445

# REPAIR ORDER - RO

Scheduled : 11/22/2020 04:09 PM

Print Date : 11/30/2020

2001 Mercedes-Benz - e36 - gas
Lic # : 312194 - PA

VIN # : WDB124092 **1F312194**
MFG Date : 11/22/2020
Current Odom : 12491

[redacted]

Last Service : No History

Elapsed : 0

| Labor Requested / Part Description | Part # | Qty | Parts List | Extended |
|---|---|---|---|---|
| *replace rear pinion seal and nut* | | | | *247.90* |
| pinion washer | washer | 1.00 | 8.68 | 8.68 |
| pinion nut | pinion nut | 1.00 | 12.24 | 12.24 |
| Gear Oil GL5 | 75W90 | 2.00 | 19.95 | 39.90 |
| rear pinion seal | pinion seal | 1.00 | 44.88 | 44.88 |

**Share Your Experience! Leave Us A Review On Facebook!**

**Parts:** 1,836.10
**Labor:** 2,309.69

**Tax:** 248.75

**Total:** 4,394.54
**Balance:** 4,394.54

hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate ne vehicle herein described on street, highways or elsewhere for the purpose to testing and/or inspection. Unless otherwise explicitly stated, there is a ninimum one (1) hour labor rate charge for any diagnostic work. An express mechanic's lien is hereby acknowledged on above car or truck to secure the mount of repairs thereto. Warranty work must be performed in our shop & cannot exceed the original cost of repair. Any vehicle left on premises for any mount of time exceeding fourteen (14) days after work is completed will be subject to a $75/ day storage fee. Any parts - new, used, or otherwise - left n premises for any amount of time exceeding thirty (30) days after work is completed will become property of Leading Edge Autosport LLC. IOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

uthorized By _____ Date _____ Time _____



Copyright (c) 2020 Mitchell Repair Information Company, LLC ropartdetail2 dj 7.2.18

# Auto Critic Inc.

1336 S Federal Hwy
Pompano Beach FL 33062
(954)786-7086
F(954)786-7084

1995 M-Benz E36 Wagon (Japan)
WDB1240921F312194

2/22/2021 – Vehicle Towed to Auto Critic : Current Mileage 12588
Customer states vehicle has no Reverse.
Start Vehicle to check for Reverse, Car Stalled During Test drive, would not stay running longer than 1-2 Mins, Was able to check that vehicle has No reverse. Pull car into building to drop transmission pan and inspect for metal shavings. Found pan filled with metal shavings.

2/24/2021- Vehicle Towed to transmission repair shop for transmission rebuild
When transmission rebuild was complete (4 weeks later, due to hard to get parts) tried to test drive car and the car would not run for longer than 1- 2 mins and would shut off.

3/24/2021- Vehicle towed back to Auto Critic Inc. Tried to drive car and car would not stay running. Start Diagnostic on why car wont stay running. Upon Inspection we found the Crankshaft Position Wiring compromised, it was broken and exposed. We Believe this compromised wire shorted a component in the Engine Control Unit. DIAGNOSTIC TOOK DAYS ! No information / Diagrams are available for this car.

4/5/2021- Remove Engine Control Unit and ASD Relay to send out for Inspection / Repair.
4/14/2021- Update – Waiting on special order parts from overseas for control unit repair.

4/27/2021- Picked up Engine Control Unit w/ OHM control Box to set Engine Control Unit. NO GUARANTEE ON REPAIR:: Vehicle started and we were able to drive vehicle for 2 Days and test transmission rebuild, vehicle now has reverse.

4/29/2021- Notified Customer to come and pick up vehicle and customer let us know he would pick up the car the following day (Friday 4/30/2021).

4/30/2021 – Customer did not show up:: Parked Vehicle in the building on Friday for the weekend. Upon returning to the shop on Monday (5/3/2021) Vehicle would no longer start, just cranks.

5/3/2021 – Notified Customer that the vehicle no longer runs.

Current Mileage 5/3/2021 :: 12603
Vehicle Drove 15 Miles Total

8/27/2021 – RELEASE OF RESPONSIBILITY – Auto Critic Inc is not responsible for the current operation of the vehicle but is more than willing to help try to get the car running.

| ITEM | QTY | PRICE | DESCRIPTION |
|---|---|---|---|
| LABOR | 0.00 | 0.00 | Customer Complaint : No Reverse - Shifting @ 5500 RPM- Holds Shift out |
| SUBLET WORK | 1.00 | 2400.00 | Sublet: TRANSMISSION REBUILD |
| KD | 1.00 | 24.50 | KICK DOWN SWITCH -wp |
| CONTROL UNIT | 1.00 | 850.00 | ENGINE CONTROL UNIT REBUILD * Special Order Parts overseas* |
| LABOR | 0.00 | 0.00 | Found Broken / Compromised Wire for Crank Sensor - Repair Wiring. |
| LABOR | 0.60 | 84.00 | Repair Short in ASD Relay |
| TOW | 1.00 | 120.00 | TOW to Transmission Shop |

*QUESTIONS:* Call us

**We are always happy to answer any vehicle service questions you have.**

**Please refer to the printed work order you received from us at the beginning of the job for contract terms, limitation of liabilities, and warranties/ guarantees pertaining to items and services listed in this work order summary.**

| | |
|---|---|
| Sublet | 2400.00 |
| Supplies | 15.00 |
| Disposal | 1.00 |
| Parts | 994.50 |
| Labor | 84.00 |
| SubTotal | 3494.50 |
| Salestax | 76.55 |
| Coupons | 0.00 |
| Deposits | 0.00 |

# AUTOMATIC TRANSMISSION REBUILD

Disassemble Transmission, discard all soft parts, clean all parts to be used in reassembly.

Replace Clutches, Bands, Seals, Gaskets, Bushings, Bearing and Internal Transmission Rings along with a new Transmission Filter.

Replace Solenoid, Planetary, & Torque Converter. Reassemble , modify and update as needed. Reassemble Rebuilt Transmission.