


3130 39th Avenue North St. Petersburg, FL 33714

GlennsMG.com

(727) 521-9890



1955 Lincoln Capri

License # ODO In:32693 Inv Date: 7/12/2018

Invoice #

VIN: BT 16717 A

ODO In:32693 Out: 32858 Color: Pink

Service Writer: Gail Lenhard

11003

Engine: V8 5.6L, 341cid, OHV, GAS, CARB

Mfg. Date:

Status: Posted

Driver: **PO** #

Trans:

Unit #

 Vehicle Problems
 Requests for Service
 Services Performed
 Hrs
 Qty
 Price
 Ext

 Check over car for condition. Check all suspension, brakes, engine running, clutch, transmission.
 0.00

Road test for noises and driveability. Check operation of all electrical accessories and lights.

0.00

Labor Service - Check over car for condition. Check all suspension, brakes, engine running, clutch, transmission. Road test for noises and driveability. Check operation of all electrical accessories and lights. See attached report for details.

0.00

Check engine compression. Remove all drums and inspect brakes. Remove right side valve cover to investigate valve noise. Discovered one rocker adjuster back out. Screw back down and noise is gone.

Take photographs of all problem areas. JAMES

Brakes					1,509.11
Labor Servi	ice - Rebuild Brake	System as needed. See detailed report. JAMES			0.00
Rebuilt	LE2005A	Brake Servo, Treadlevac, Rebuilt	1.00	551.47	551.47
New	BHKF	Brake Cylinder Kit, w/ Hoses, Front	1.00	215.38	215.38
New	BHKR	Brake Cylinder Kit w/ Hoses, Rear	1.00	215.38	215.38
New	BLSW	Brake Light Switch	1.00	41.67	41.67
New	CNF-3	Brake Pipe, 3/16 Cunifer / ft	10.00	3.33	33.30
New	H1457-2	Brake Hose Lock (SKU#10863877)	1.00	5.60	5.60
New	CNB320	Brake Pipe, NiCopp	1.00	18.28	18.28
New	CNB351	Brake Pipe, NiCopp	2.00	23.98	47.96
New	5088	a/c 1/2"drain tube elbow	1.00	4.40	4.40
New	27230	Brake Booster Hose 11/32	6.00	6.24	37.44
New	5203	Hose Clamp #6	6.00	1.96	11.76
New	CNB330	Brake Pipe, NiCopp	1.00	17.59	17.59
New	SBF-12	Brake Fluid, DOT 5 Silicone, Pint	2.50	15.91	39.78
New	141-743	Flasher Bracket, Round Style	1.00	5.64	5.64
New	EL12	Electronic Flasher, Two Spade Terminal	1.00	23.62	23.62
New	1157	Bulb	4.00	3.28	13.12
New	1156	Bulb	2.00	3.92	7.84
New	06008G	Brake Shoe Set, Front	1.00	101.67	101.67
New	UPS	Shipping from Kanter	1.00	39.00	39.00
New	ICR37	Coil Resistor	1.00	24.53	24.53
Used	4000F	Holley 4000 Carburetor Float, Good Condition - USED	1.00	26.27	26.27
New	92418	Cooling Fitting	1.00	27.41	27.41
Front Suspens	ion				2,160.80

Front Suspens	sion				2,100.00
Labor Serv	rice - Rebuild front sus	spension as needed. See detailed report. JAMES			0.00
New	LA3025A	Upper Rebound Pair	1.00	108.33	108.33
New	LD3020A	Lower Rebound RH	1.00	66.67	66.67
New	LD3019A	Lower Rebound LH	1.00	66.67	66.67
New	LA3068A	Bushing Set, Upper Front	1.00	120.97	120.97
New	B4A3069C	Bushing Set of 4, Lower Control Arm	2.00	120.97	241.94
New	B5A5493	Sway Bar Bushing	2.00	58.33	116.66
New	B8LY3A130A	Outer Tire Rod	2.00	120.97	241.94
New	LA3304A	Center Drag Link Repair Kit	1.00	404.41	404.41
New	B8LY3280A	Inner Tie Rod	2.00	192.31	384.62
New	1770	Osha Black Paint	1.00	11.38	11.38
New	02082E	Shock Absorber Set of Four	1.00	322.06	322.06
New	UPS	Shipping from Kanter	1.00	35.00	35.00



3130 39th Avenue North St. Petersburg, FL 33714

GlennsMG.com

(727) 521-9890

	_				Invoice #	11003
, mg	1	1955 Lincoln Capri	License #		Inv Date: 7/12/2018	
New New	31019 98105G	Bushing Set, Swaybar End Lin Bushing Set, Swaybar Endlink	k	2.00 1.00	9.04 22.07	18.08 22.07
Cooling Syste	m					1,514.83
Labor Serv	vice - Rebuild cooling sys	stem as needed. See detailed repo	rt. JAMES			0.00
New	EBJ-88502C	Water Pump w/ Gasket and By	pass Hose	1.00	250.00	250.00
New	LA8260B	Upper Radiator Hose, Molded		1.00	66.67	66.67
New	LA88277B	Lower Radiator Hose		1.00	58.33 58.33	58.33
New New	EAD-8575D 17370	Thermostat 160 w/ Gasket Belt		1.00 1.00	15.55	58.33 15.55
New	5/8 INCH	Heater Hose		3.00	3.16	9.48
New	AF2100	Coolant, Prestone Extended Li	fe 5/150.50/50	5.00	19.98	99.90
New	834-825	Cap, Radiator, 13 Lbs		1.00	6.57	6.57
Sublet	RADIATOR REPAIR	Recore Radiator / HD		1.00	950.00	950.00
Electrical Con	version to 12V					1,864.38
Labor Serv	rice - Electrical Repairs a	as needed. See detailed report. JA	MES			0.00
New	F5456YK	Alternator Conversion Kit, 12V		1.00	617.50	617.50
New	VRWTS	12 to 6 Volt Step-Down Unity, Window	Electric Seat,	1.00	264.63	264.63
New	H6024	Halogen Lamp		2.00	27.83	55.66
New	26MF	Battery - 540CCA-World Source	e One	1.00	113.45	113.45
Core	26MF	Core Received		1.00	0.00	0.00
New	S63	Starter Solenoid, 4-Post, 12V		2.00	34.76	69.52
New	LLB989	Bulb		15.00	1.88	28.20
New	85104	Horn Kit, Hella		1.00	62.24	62.24
New	8004BCB	Battery Cable , Black		1.50	4.53	6.80
New	8004BCR	Battery Cable , Red		1.00	4.72	4.72
New	1823HD	Battery Cable Lug 3/8		1.00	2.76	2.76
New	1822HD	Battery Cable Lug 5/16		3.00	2.76	8.28
New	53645M	Heat Shrink Black		0.50	5.12 5.12	2.56 2.56
New New	53646M 144-200	Heat Shrink Red Lamp, License Plate		0.50 1.00	27.68	2.56
New	0 332 019 150	Relay		2.00	17.29	34.58
Used	USED	Top Motor, 12V, Good Condition	on Used	1.00	338.24	338.24
Sublet		Rebuild Starter	, , , , , , , , , , , , , , , , , , ,	1.00	225.00	225.00
Parts sale only	v					1,054.45
·	, vice - MISCELLANEOUS	SPARTS				0.00
New	70981	Acorn Nut. Stainless Steel. Va.	lve Cover	4.00	7.55	30.20
New	AF2100	Coolant, Prestone Extended Li		5.00	19.98	99.90
Used	N	Letter "N" Used	,	1.00	9.43	9.43
New	REPRO	Shop Manual		1.00	50.00	50.00
New	2438	Spark Plug, NGK WR5		8.00	4.45	35.60
New	<i>9175</i>	Ignition Wire Set		1.00	36.55	36.55
New	G141	Ignition Condenser		1.00	10.96	10.96
New	FL1A	Oil Filter		4.00	8.19	32.76
New	A98V	Ignition Points		1.00	16.07	16.07
New	17TG	Speedometer Drive Gear		1.00	75.00	75.00
New	2050 PENN	20w50 Penn Grade 1		6.00	9.22	55.32
New	2050 SE16	Castrol GTX 20W/50 SeaFoam		13.00 1.00	6.82	88.66 15.44
New New	SF16 CQ420	Searoam Automatic Transmission Fluid	Devron	1.00 4.50	15.44 7.19	15.44 32.36
New New	CQ420 CQ650	Oil, CarQuest House Brand, 20		4.50 1.00	7.19 4.55	32.36 4.55
Sublet	MISC	Manufacture Speedometer Cal		1.00	27.00	27.00
New	U-16	Wiper Refill, 16", Anco	210 II II IOI	1.00	13.96	13.96
New	4509	Rubberized Undercoating		1.00	19.53	19.53
Used	USED	Courtesy Light Switch		1.00	41.67	41.67
New	470-757	Washer		1.00	1.95	1.95



3130 39th Avenue North St. Petersburg, FL 33714

Glenns MG. com

(727) 521-9890

				Invoice #	11003
mig	19	55 Lincoln Capri Licens	e #	Inv Date: 7/12/201	8
New	OP6091	Oil Pressure Sending Unit	1.00	38.45	38.4
New	69906	Pipe Plug 3/8	4.00	4.02	16.0
New	325-130	Clevis Pin, 1/4 X 5/8	1.00	1.11	1.1
New	55942	Mr Moly Break-In Lubricant	1.00	25.65	25.6
New	GAS	Non-Ethanol Gasoline - 13 Gallons	1.00	40.00	40.0
Sublet	SPEEDOMETER	Repair Speedometer	1.00	236.25	236.2
burator reb	uild and fuel system.				945.
Labor Servi	ice - Carburetor and fuel s	ystem repairs. See detailed report. JAMES			0.0
New	477060E	Fuel Pump, Facet Interupter	1.00	124.75	124.
New	103 988 01 11	Air Cleaner Mount	2.00	4.67	9.
New	69243	Fuel Fitting, 1/8" NPT x 5/16" Barb 90 Degree Elbow	1.00	7.53	7.
New	TNK-556FS	Sending Unit, Fuel Tank	1.00	66.65	66.
New	45-258	Electric Choke Cover, Holley	1.00	48.25	48.
Sublet	CARB	Rebuild Carburetor	1.00	225.00	225.
New	CIN-SN39	Fuel Tank Sender	1.00	73.32	73.
New	FEDEX	Shipping from Summit Racing	1.00	30.24	30.
New	282-630	Ferrule, Gas Filler Neck	1.00	3.21	3.
New	GAS	Non Ethanol Gasoline - 17.845 Gallons	1.00	56.00	56.
New	C147	Distributor Cap	1.00	26.05	26.
New	D130P	Distributor Rotor	1.00	10.72	10.
New	PEX1282	Pertronix Electronic Ignition 8 - Cyl Neg Ground		153.23	153.
New	AP500	Accelerator Pump Cup Holley 4000	1.00	11.45	11.
New	3-110	Rebuild Kit, Holley 4bbl Teapot	1.00	100.00	100
ine Repair					3,503.
		eded. See detailed report. JAMES		40.00	0.
New	HT-2083	Lifter	16.00	13.00	208.
New	REPRO GASKET SET	Intake Manifold Gasket Set	1.00	82.50	82.
New	B2TZ6506A	Valve Cover Gasket Set	1.00	58.33	58.
New	23668H TC487	Timing Chain	1.00	78.72	78.
Used	RECON	Valve Train, Good Condition, Used	2.00	175.00	350
New	23644J TSCA215T	Cam Gear	1.00	119.38	119.
New	23645F TSCR252	Crank Gear	1.00	76.67	76
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	23653K	Valve Spring	16.00	9.72	155
New			10.00		
-	368REPRO	Engine Gasket Set	1.00	286.76	286
New	368REPRO MOUNTSET				
New New		Engine Gasket Set Engine Mount Set	1.00	286.76	294
New New New New	MOUNTSET RS3737G	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads	1.00 1.00 1.00	286.76 294.12 260.29	294. 260.
New New New New Rebuilt	MOUNTSET RS3737G CAM SHAFT REGROUN	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground	1.00 1.00 1.00 1.00	286.76 294.12 260.29 470.59	294. 260. 470.
New New New New	MOUNTSET RS3737G	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground Push Rod Recondition both cylinder heads, supply new	1.00 1.00 1.00	286.76 294.12 260.29	294. 260. 470. 155.
New New New New Rebuilt New Sublet	MOUNTSET RS3737G CAM SHAFT REGROUN B6LY-6565 MACHINE SHOP	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground Push Rod	1.00 1.00 1.00 1.00 6.00	286.76 294.12 260.29 470.59 25.86	294. 260. 470. 155. 907.
New New New New Rebuilt New Sublet	MOUNTSET RS3737G CAM SHAFT REGROUN B6LY-6565 MACHINE SHOP mmary or Details.	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground Push Rod Recondition both cylinder heads, supply new	1.00 1.00 1.00 1.00 6.00	286.76 294.12 260.29 470.59 25.86	294. 260. 470. 155. 907.
New New New New Rebuilt New Sublet  Clock Sul Labor Servi JAMES	MOUNTSET RS3737G CAM SHAFT REGROUN B6LY-6565 MACHINE SHOP mmary or Details. ice - 7/19 - 10/1: Accumul	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground Push Rod Recondition both cylinder heads, supply new exhaust valves  lated time from Job Clock. Details attached.	1.00 1.00 1.00 1.00 6.00 1.00	286.76 294.12 260.29 470.59 25.86 907.20	294. 260. 470. 155. 907. <b>19,380.</b> 22,135.
New New New Rebuilt New Sublet  e Clock Sul Labor Servi JAMES  Labor Servi	MOUNTSET RS3737G CAM SHAFT REGROUN B6LY-6565 MACHINE SHOP mmary or Details. ice - 7/19 - 10/1: Accumul	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground Push Rod Recondition both cylinder heads, supply new exhaust valves	1.00 1.00 1.00 1.00 6.00 1.00	286.76 294.12 260.29 470.59 25.86 907.20	294 260 470 155 907 <b>19,380</b> 22,135
New New New Rebuilt New Sublet  e Clock Sul Labor Servi jAMES Labor Servi improper pa	MOUNTSET RS3737G CAM SHAFT REGROUN B6LY-6565 MACHINE SHOP  mmary or Details. ice - 7/19 - 10/1: Accumul ice - Refund of hours for til arts. JAMES	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground Push Rod Recondition both cylinder heads, supply new exhaust valves  lated time from Job Clock. Details attached.  me spent re-performing repairs due to faulty or m Job Clock. Details attached. Strip and refinish	1.00 1.00 1.00 1.00 6.00 1.00	286.76 294.12 260.29 470.59 25.86 907.20	286. 294. 260. 470. 155. 907. <b>19,380.</b> 22,135.
New New New Rebuilt New Sublet  e Clock Sul Labor Servi jAMES Labor Servi improper pa	MOUNTSET RS3737G CAM SHAFT REGROUN B6LY-6565 MACHINE SHOP  mmary or Details. ice - 7/19 - 10/1: Accumul ice - Refund of hours for tiarts. JAMES ice - Accumulated time fro	Engine Gasket Set Engine Mount Set Gasket Set, Engine, Composite Heads NDCam Shaft, Reground Push Rod Recondition both cylinder heads, supply new exhaust valves  lated time from Job Clock. Details attached.  me spent re-performing repairs due to faulty or m Job Clock. Details attached. Strip and refinish	1.00 1.00 1.00 1.00 6.00 1.00	286.76 294.12 260.29 470.59 25.86 907.20 95.00 95.00	294. 260. 470. 155. 907. <b>19,380.</b> 22,135.

### **Notes**

There is some leakage from the transmission front seal. Transmission reseal or overhaul recommended.



3130 39th Avenue North St. Petersburg, FL 33714

GlennsMG.com

(727) 521-9890

Invoice #

11003

1955 Lincoln Capri

License #

Inv Date: 7/12/2018

Continued from previous page

#### Warranty We warran

We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied.

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that Glenn's MG Repair is not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

If the vehicle is not picked up within 5 days of being notified that the work is completed, there may be a storage fee of \$10.00 per day added to the bill.

X

Customer agrees to perform the obligations set forth by the card member's agreement with the issuer.

Posted 11/05/18 3:36PM

Visa 6,152.89 Parts 9,982.10 Credit Used 15,000.00 19,380.00 Labor Credit Used 3,000.00 Sublet 2,570.45 Credit Used 10,000.00 Add On Charges 1.50

 Sub Total
 31,934.05

 Sales Tax (DEF)
 2,218.84

**Invoice Summary** 

Discard old parts Original Estimate: Total 34,152.89

Page 4 of 4



# Glenn's M

3130 39th Avenue North St. Petersburg, FL 33714

GlennsMG.com

(727) 521-9890



### 1955 Lincoln Capri

VIN: BT 16717 A

Engine: V8 5.6L, 341cid, OHV, GAS, CARB Mfg. Date:

Trans:

License # 096 10Z

ODO In:33024 Out: 33034

Color: Pink

Unit#

Inv Date: 12/13/2018

Invoice #

Service Writer: Glenn Lenhard

11216

Status: Posted Driver: Wright, Chip

PO#

Vehicle Proble	ems Requests	for Service	Services Performed	Hrs	Qty	Price		Ext
Transmission is leaking. Recommend full rebuild.								2,170.00
	ce - Sublet Repair or S TRANSMISSION		itomatic transmission		1.00	2,150.00		0.00 2,150.00
New	GAS	7.551 Gallons Non-Ethanol Gasoline			1.00	20.00		20.00
Radiator is leaking. 0.00								

Radiator is leaking.	0.00
Labor Service - Remove and reinstall radiator after repair. N/C JAMES	0.00

Warranty	Posted 1/30/19 11:45AM	Invoice Summary	
We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied.	Credit Used 2,321.90		20.00
I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that Glenn's MG Repair is not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.  If the vehicle is not picked up within 5 days of being notified that the work is completed, there may be a storage fee of \$10.00 per day added to the bill.			
XSignature		,	70.00 51.90
Page 1 of 1 Discard old parts	Original Estimate:	Total 2,3	21.90



3130 39th Avenue North St. Petersburg, FL 33714

GlennsMG.com

(727) 521-9890



### 1955 Lincoln Capri

Capri License # 096 10Z ODO In:33034 0

VIN: BT 16717 A Color: Pink

Engine: V8 5.6L, 341cid, OHV, GAS, CARB

Trans:

cense # 096 10Z Inv Date: 1/30/2019 DO In:33034 Out: 33034

or: Pink Service Writer: Glenn Lenhard

Mfg. Date: Status: Posted
Driver: Wright, Chip

Invoice #

11287

Unit # PO #

ehicle Probl	ems Reques	sts for Service	Services Performed	Hrs	Qty	Price	Ext
ody work/pai	nt				'	'	4,411.58
			ge boxes and refinish. Repair and ders, hood and trim. DARIN, RAUL	42.30		85.00	3,595.50
Used	USED	Hinge Set, U	Ised		1.00	380.00	380.00
New	UPS	Shipping for	Hinges		1.00	35.00	35.00
New	70885	Tangier Rose	e, color match paint / Quart		2.00	200.54	401.08
ditional part	ts and labor perform	ned not accident re	elated.				1,321.19
panel and s air ducting	straighten latch and s	afety. Repair brokei er inlet. Install new f	corner of hood. Remove latch n air control cable on right. Replace render-to-body seals. Drill holes for	6.00		85.00	510.00
New	AUVECO		and J Nut Set		1.00	30.00	30.00
New	BF-16812-A	Hood Hinge			2.00	27.18	54.36
New	UPS		ก C&G Ford Parts		1.00	14.60	14.60
New	OM-8725-A		h Air Duct Connector		4.00	7.45	29.80
New	BA-7001878-C	Connector A			2.00	27.18	54.36
New	BD-16754-A	Hood Bumpe			1.00	21.73	21.73
New	BA-16761	Hood Buffer			1.00	27.18	27.18
New	B5A-16170-A		ender Splash Apron, 72"		2.00	18.09	36.18
New	1030-4000	Air Intake Du			1.00	56.06	56.06
New	30023	3M 90 Spray	,		0.50	21.38	10.69
New	353483-S		Fender Bolt, Black		4.00	2.00	8.00
New	8A-16798-S	Hood Hinge			4.00	5.57	22.28
New	USPS		m Dennis Carpenter		1.00	9.99	9.99
Look at pic to determin	tures to determine wh	nere sideview mirror r this position. Insta	oracket. Blast and paint washer lid. r should go. Have Brian hold mirror all mirror. Install washer bottle and	3.50		105.00	367.50
New	GAS		Ion-Ethanol Gasoline		1.00	46.00	46.00
New	0125675		ed, 10-32 Thread, 1/2" Tall		2.00	1.41	2.82
New	AF2100	,	stone Extended Life 5/150,50/50		0.50	19.98	9.99
14011	145-795	Switch, Batte			1.00	9.65	9.65

#### Notes

Insurance is through American Modern Claim number is 489199AA Adjuster is Marc McQuitty His email is mmcquitty@amig.com His phone is 800-375-2075



3130 39th Avenue North St. Petersburg, FL 33714

GlennsMG.com

(727) 521-9890

Invoice #

11287



Warranty

1955 Lincoln Capri

License # 096 10Z

Inv Date: 1/30/2019

**Invoice Summary** 

Continued from previous page

Page 2 of 2 Discard old parts	Original Estimate:	6,134.06	Total	6,134.06
Customer agrees to perform the obligations set forth by the card member's agreement with the issuer.			Sub Total Sales Tax (DEF)	5,732.77 401.29
I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that Glenn's MG Repair is not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.  If the vehicle is not picked up within 5 days of being notified that the work is completed, there may be a storage fee of \$10.00 per day added to the bill.				
We warranty our labor service and new parts for 12 months or 6000 miles, whichever occurs first. If our repair or replacement part fails, you must return your vehicle to us and we will repair or replace those items free of charge. There is no other warranty written or implied.	Visa Credit Used Credit Used	3,955.96 178.10 2,000.00	Parts Labor	1,259.77 4,473.00

Posted 8/08/19 1:43PM



# Glenn's A

3130 39th Avenue North St. Petersburg, FL 33714

GlennsMG.com

(727) 521-9890



Warranty

### 1955 Lincoln Capri

VIN: BT 16717 A

Engine: V8 5.6L, 341cid, OHV, GAS, CARB Mfg. Date:

Trans:

License # 096 10Z

Out: 33119 ODO In:33034

Posted 9/09/19 1:19PM

Color: Tangier Rose

Unit#

Inv Date: 8/08/2019

Invoice #

Service Writer: Gail Lenhard

**Invoice Summary** 

11520

Status: Posted Driver: Wright, Chip

PO#

Vehicle Prob	lems R	equests for Service	Services Performed	Hrs	Qty	Price	Ext
lood hinge					·		541.95
Labor Serv SKIP	rice - Cut open r	new hinge pair and mount	new hinges to original air boxes.	12.00			0.00
New	BA-16796/7	Hinge Set, N	'ew		1.00	499.00	499.00
New	UPS	Shipping from	Shipping from Early Ford Store		1.00	42.95	42.95
Clean plugs a	nd ready for de	livery.					33.00
Labor Servitest. JAMI		safety items, lights, tire pr	essures, fluid levels. Final road				0.00
New	GASOLINE	Non-Ethanol	Gasoline, 6.875 Gallons		1.00	20.00	20.00
New	GAS	4.89 Gallons	Non Ethanol Gasoline		1.00	13.00	13.00

We warranty our labor service and new parts for 12 months or whichever occurs first. If our repair or replacement part fails, you	ou must return your		Parts Parts Discount	574.95 -574.95
vehicle to us and we will repair or replace those items free of c other warranty written or implied.	harge.There is no			
I hereby authorize the repair work hereinafter set forth to be done along with the ne agree that Glenn's MG Repair is not responsible for loss or damage to vehicle or ar case of fire, theft, or any other cause beyond our control or for any delays caused it transporter. I hereby grant you and/or your employees permission to operate the ve streets, highways, or elsewhere for the purpose of testing and/or inspection. An exphereby acknowledged on above vehicle to secure the amount of repairs thereto.  If the vehicle is not picked up within 5 days of being notified that the work is complestorage fee of \$10.00 per day added to the bill.	ticles left in vehicle in by the supplier or hicle herein described on oress mechanic's lien is			
X Signature			Sub Total Sales Tax (DEF)	
Page 1 of 1	Discard old parts	Original Estimate:	Total	