

GEORGE WILLIAMSON AUTO ELECTRIC INC.

32 FREIGHT ST.

Wtby., CT 06702-0000

Shop Phone: (203) 755-5299

Repair Order

31662

Estimate Ref #0

Date Printed: 05/10/2021

Printed Time: 6:23 pm

Hat/Ref:

Time Promised:

2009 ASTON MARTIN DBS V12 6.0L 5935CC FI GAS N

VIN: SCFAB06D49GE00855

License: EX M16

Mileage In: 9,411

Date Written: 05/10/2021

Unit #:

Mileage Out: 9,411

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	maintenance				
Labor 1.0	Work Requested - maintenance		4.00	105.00	420.00
	Work Performed - perform 10 k maintenance. change oil and filter. replace air and cabin filters. bleed and flush brake system . reset service interval light				
Part	Oil Filter		1.00	54.22	54.22
Part	oil drain gasket		1.00	7.94	7.94
Part	oil drain plug		1.00	27.62	27.62
Part	cabin air filters		1.00	109.96	109.96
Part	air filters		2.00	106.33	212.66
Part	Brake Fluid		1.00	36.02	36.02
Part	oil ow40		11.00	12.00	132.00

Payment Date	Type	Method	Amount
--------------	------	--------	--------

Payment Totals:

Parts: \$580.42

Labor: \$420.00

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$0.00

Supplies: \$0.00

Tax Total: \$63.53

Repair Order Total: **\$1,063.95**

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By _____

Date _____

Time _____

GEORGE WILLIAMSON AUTO ELECTRIC INC.

32 FREIGHT ST.

Wilby, CT 06702-0000

Shop Phone: (203) 755-5299

Repair Order

27886

Estimate Ref #0

Date Printed: 04/16/2019

Printed Time: 4:25 pm

Hat/Ref: *Saturday Morning*

Time Promised:

2009 ASTON MARTIN DBS V12 6.0L 5935CC FI GAS N

VIN: SCFAB06D49GE00855

License: EX M16

Mileage In: 9,104

Date Written: 04/16/2019

Unit #:

Mileage Out: 9,104

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	service				
Labor 1.0	Work Requested - service		2.00	95.00	190.00
	Work Performed - change oil and filter. reset maintenance light. flush brake fluid				
Part	synthetic 0w40		11.00	12.00	132.00
Part	Oil Filter		1.00	74.22	74.22
Part	drain plug and gasket		1.00	37.03	37.03
Part	o ring throttle body		1.00	11.80	11.80

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$255.05

Labor: \$190.00

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$0.00

Supplies: \$0.00

Tax Total: \$28.27

Repair Order Total: \$473.32

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By _____

Date _____

Time _____



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CUSTOMER NO. 24539		ADVISOR ARMAND		TAX NO. 29 0855	INVOICE DATE 01/06/16	INVOICE NO. ASCS66383
LABOR RATE 169.00		LICENSE NO.		MILEAGE 8,088	COLOR LIGHTNING S	STOCK NO.
YEAR/MAKE/MODEL 09/ASTON MARTIN/DBS/2DR CPE		VEHICLE I.D. NO. SCFAB06D49GE00855		DELIVERY DATE		DELIVERY MILES
F.T.E. NO.		P.O. NO.		WARRANTY EXP. DATE		PRODUCTION DATE
BUSINESS PHONE		COMMENTS		R.O. DATE 01/04/16		

CELL: 860-682-0700

JOB# 1 CHARGES----- MO: 8107

LABOR-----
JOB# 1 00ASZ2YR TWO YEAR SERVICE HOURS: 9.00 TECH(S): 95 1521.00

CLIENT STATES CHECK THE VEHICLE FOR THE YEARLY SERVICE.
PERFORM CLIENT APPROVED TWO YEAR INTERVAL SERVICE
DISCOUNT 10% FOR WINTER SERVICE SPECIAL

PERFORMED TWO YEAR SERVICE AS PER ASTON MARTIN MAINTENANCE SCHEDULE. RESET SERVICE REMINDER LIGHT, CHECKED AND CHARGED BATTERY, CHECKED AND CLEARED COMPUTER CODES, SERVICED BRAKES, CHECKED AND SET ALL TIRE PRESSURES, CHECKED AND TOPPED UP FLUIDS AS NEEDED, PERFORMED COMPLETE VEHICLE INSPECTION. TREAD DEPTH MEASURES 4.2/4.1MM IN THE FRONT AND 2.8/2.2MM IN THE REAR. BRAKES MEASURE 8MM IN THE FRONT AND 6.5MM IN THE REAR TO THE SENSORS. REMOVED INSULATION FROM UNDER FIREWALL GROUNDS. REPLACED KEY FOB BATTERY. ROAD TESTED CAR. ALL OK.
DEPENDING ON THE DRIVING MAY NEED REAR TIRES IN THE NEXT COUPLE OF THOUSAND MILES.

PARTS-----	QTY-----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-----	
	1	PK39	2.4.6 YEAR SERVICE	****	****
	12	G-0529302-B	1QT ENGINE OIL	10.45	125.40
	1	2032	BATTERY	9.30	9.30
	1	4G43-13ZE1-AA-PK	POLLEN FILTER	105.59	105.59
		SOLD AS PAIR			
	2	4G43-9601-AB-PK	AIR FILTER	102.10	204.20
	1	AG43-6714-AA-PK	V12 OIL FILTER	53.20	53.20
	1	1R12-08-10317-PK	O-RING	7.53	7.53
	1	4G43-04-10205-PK	OIL DRAIN PLUG	27.58	27.58
	1	700781-PK	BRAKE FLUID	35.24	35.24
	1	WSW	WSW SOLVENT	3.10	3.10
	1	02456	BRAKECLEAN	2.85	2.85
			TOTAL - PARTS		573.99

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----	
	TA10	TOTAL RO 10% ASTON		-209.50
			TOTAL - MISC	-209.50

JOB# 1 TOTALS-----
LABOR 1521.00
PARTS 573.99
MISC -209.50

JOB# 2 CHARGES----- JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL 1885.49

LABOR-----
JOB# 2 85ASZ ACCESSORIES HOURS: 1.50 TECH(S): 96 253.50
CLIENT STATES HARD WIRE CABLE FOR RADAR DETECTOR.

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere in the Continental US.
- Complete body shop

All these services are available for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO. 24539	ADVISOR ARMAND	TAG NO. 29 0855	INVOICE DATE 01/06/16	INVOICE NO. ASCS66383
	LABOR RATE 169.00	LICENSE NO.	MILEAGE 8,088	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/2DR CPE			DELIVERY DATE
	VEHICLE I.D. NO. SCFAB06D49GE00855			WARRANTY EXP. DATE
	P.T.E. NO.			P.O. NO.
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS		MO: 8107

REMOVED HEADER RAIL TRIM, A-C PILLAR TRIM, PASSENGER SIDE CARPET AND GLOVE BOX. ROUTED PHONE WIRING FROM CLIENTS REQUESTED LOCATION TO BEHIND THE DASH. REASSEMBLED REMOVED UPPER TRIM. GAINED ACCESS TO WIRING BEHIND DASH AND WIRED IN POWER TO KNOWN SWITCHED POWER AND USED A STABLE GROUND. SECURED HARDWARE KIT AND REINSTALLED GLOVE BOX AND CARPET. TESTED FOR POWER AND GROUNDS. ALL OK.

JOB# 2 TOTALS-----LABOR 253.50

JOB# 2 JOURNAL PREFIX ASCS JOB# 2 TOTAL 253.50

JOB# 3 CHARGES-----LABOR 0.00

JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

TOTALS-----TOTAL LABOR... 1774.50
TOTAL PARTS... 573.99
TOTAL SUBLET... 0.00
TOTAL G.O.G... 0.00
TOTAL MISC CHG... 15.00
TOTAL MISC DISC... -209.50
TOTAL TAX..... 150.08
TOTAL INVOICE \$ 2304.07

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere in the Continental US.
- Complete body shop

All these services are available for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

The Reynolds and Reynolds Company ENAMRIVE CC235816 Q (07/13)

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

Aston Martin Vehicle Maintenance Check Sheet

Always use body interior and exterior protection and the correct grades of lubricants and fluids. Tick the box in column "C" when the check is complete and tick in column "A" if corrective work is necessary.

FULLY CLEAN THE VEHICLE AND THE WORK AREA.

Owner: [REDACTED]

Vehicle R: [REDACTED]

Model/Derivative: DB5

VIN: E00855

Date: 1/5/16

Key No.:

Odometer (km/mls): 8088

Dealer Job/Invoice No.: 66383

12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km			
x	x	Install the vehicle protection kit and wing covers	C	A
x	x	Do a check of the Campaign Status		

Fluid, Filters and Inspect for Leaks				
x	x	Examine the engine for oil leaks	C	A
x	x	Renew the engine oil (use the correct specification)		
x	x	Renew the engine oil filter		
-	x	Renew the air cleaner element(s) (V12 Engines)		
Every 3 years or 30,000 mls (48,000 km)		Renew the air cleaner element(s) (V8 Engines)		
x	-	Examine the transmission and final drive for condition and leaks. Fill if necessary		
Every 6 years 60,000 mls 96,000 km	Every 10 years 100,000 mls 160,000 km	Do a check of the manual transaxle oil level. Fill if necessary		
Every 4 years or 40,000 mls (64,000 km)		Renew the manual transaxle oil and clean the filter		
Every 4 years or 40,000 mls (64,000 km)		Renew the automatic differential oil and clean the filter		
x	x	Examine the engine cooling and occupant heating system for condition and leaks. Fill if necessary		
Every 5 years or 50,000 mls (80,000 km)		Renew the engine coolant - 50/50 concentration		
x	x	Examine the condition and attachment of the fuel system, hoses, pipes and unions for leaks		
Every 12 months		Renew the brake/clutch fluid (use the correct specification) (V12 engines)		
Every 24 months		Renew the brake/clutch fluid (use the correct specification) (V8 engines)		
x	x	Examine the brake/clutch fluid level. Fill if necessary		
x	x	Examine the condition and attachment of the power steering system, hose, pipes and unions		
x	x	Examine the power steering fluid level and fill if necessary		
x	x	Examine the condition and attachment of the brake system, hoses, pipes and unions		
x	x	Examine the condition of the suspension dampers for leaks		
x	x	Examine the condition of the exhaust system for leaks		
x	x	Examine the level of the the windscreen and headlamp washer reservoir. Fill if necessary		
x	x	Do a check of the exhaust bypass valve operation at 800/3000 rpm		

Model Applicability:

V8 and V12 Vantage, Vantage S, DB9, DBS, Rapide, Virage. For all other models please use the applicable Maintenance Check Sheet.

Note: For maximum customer satisfaction, we recommend that you do a road test before the maintenance is done, and again when the work is complete.

x	x	Examine the condition and attachment of the air conditioning system, hoses, pipes and unions. Use UV to do a check for leaks		
-	x	Renew the pollen filter		

12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km			
x	x	Examine the condition, attachment, correct operation and lubricate all door locks, latches, hinges and joints.	C	A
x	x	Examine the condition, attachment, correct operation and lubricate the bonnet catch.		
x	x	Examine the condition, attachment, correct operation and lubricate the secondary bonnet catch(es).		
x	x	Examine the condition and tension of the accessory drive belt. Adjust or replace if necessary		
x	x	Examine the cooling pack radiator, condenser and transmission cooler for blockage and unwanted material. Clean if necessary		
x	x	Examine the condition and attachment of the cooling system hoses		
x	x	Examine the condition and attachment of the air conditioning hoses		
Every 4 years or 40,000 miles (64,000 km)		Clean the throttle butterflies (V12 only)		
x	x	Examine the condition and attachment of the wiper blades. Replace if necessary		
x	x	Examine the condition and operation of all seat belts and buckles		
x	x	Examine the condition and attachment of the rear view mirror		
x	x	Examine the condition and attachment of the handbrake and the handbrake pads		
x	x	Examine the condition, attachment and adjustment of the handbrake cables. Adjust if necessary		
x	x	Examine the condition of the brake pads, brake discs and calipers. At 60% wear, replace the brake pads and pad wear sensors. For CCM Brakes, at every 3rd pad change, clean, dry, weigh and examine the condition of the brake discs		
x	x	Examine the condition and attachment of front brake disc shields for fatigue, cracks and the clearance from the discs		
x	x	Examine the condition and attachment of all suspension, ball joints, gaiters, bushes and fixings		
-	x	Examine the condition and attachment of the driveshafts		
x	x	Examine the condition and attachment of the exhaust system, mountings and heatshields		
-	x	Examine the condition and attachment of the wheel arch liners and the underbody protection		

Maintenance time intervals should always be obeyed, even with low service mileages, to keep the vehicle at the best performance and condition.

Issue 3, After Sales Operations, July 2012

Aston Martin Vehicle Maintenance Check Sheet

12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km			
Every 70,000 mls (112,000 km)		Electrical Function Test	C	A
x	x	Renew the spark plugs	✓	
x	x	Measure and record the battery voltage	✓	
x	x	Examine the condition and attachment of the battery connections. Adjust if necessary	✓	
x	x	Do a functional test of the battery disconnect switch	✓	
x	x	Examine the condition and attachment of all lamp units	✓	
-	x	Do a check of the headlamp alignment. Adjust if necessary	✓	
x	x	Do a functional test of all of the lights and the auto-sense function	✓	
x	x	Do a functional test of all warning indicators	✓	
x	x	Do a functional test of the audible warnings and security system	✓	
x	x	Do a functional test of the horns	✓	
x	x	Do a functional test of the windscreen wipers and auto-sense function	✓	
x	x	Do a functional test of the windscreen and headlamp washers	✓	
x	x	Examine the condition and attachment of the door mirrors	✓	
x	x	Do a functional test of the fold-back door mirrors	✓	
x	x	Do a functional test of the electrically operated windows	✓	
x	x	Do a functional check of the service indicator. Reset the indicator	✓	
x	x	Renew the batteries in the remote key fobs	✓	
x	x	Renew the tracker tags (where applicable)	✓	

Anti Corrosion Check		C	A
x	x	Examine the body panels and under body for corrosion. Work from the inside out (do not include stone chips)	✓

Comments	

Technician Name	Dealer Stamp
Sign and Date	Miller Motorcars, Inc. 186 Magee Avenue Stamford, CT 06902

12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km			
		Wheels and Tyres Check	C	A
x	x	Make sure that the tyres are the correct size, type and orientation	✓	
x	x	Measure and record the tyre tread depth	✓	
-	x	Examine the tyres for uneven or excessive wear or damage	✓	
x	x	Measure and if necessary, adjust the tyre pressures	✓	
x	x	Do a torque check of the road wheel nuts	✓	
x	x	Examine the road wheel rims for inside or outside damage. Record all damage	✓	
x	x	Make sure that the colour coded tyre pressure monitor system valve caps are on the correct wheels (if applicable)	✓	
x	x	Do a functional test of the tyre pressure sensors	✓	
x	x	Do a check of the date of the tyre inflation kit	✓	

Final Checks		C	A
x	x	Degrease the windscreen	✓
x	x	Do a road test	✓
x	x	Do a functional test of the ABS and the traction control operation	✓
x	x	Make sure that the drain for the fuel filler bowl is clear	✓
x	x	Do a functional test of the adaptive damping system	✓

Tyre Wear Report	Outer	Centre	Inner	Outer	Centre	Inner
	Across Tyre			Across Tyre		
CW Rotation	Left Front (mm)			Right Front (mm)		
Valve						
90°	4.2 mm			4.1 mm		
120°						
270°						
Tyre Pressure						
CW Rotation	Left Rear (mm)			Right Rear (mm)		
Valve						
90°	2.8 mm			2.2 mm		
120°						
270°						
Tyre Pressure						

Fuel Level	Open Circuit Battery Voltage	To remove the surface charge:
Record the fuel level when the vehicle arrives at your Dealership. Always fill the fuel tank before you return the vehicle (chargeable)	12.7 Volts	Set the ignition to ON Set the headlamps to ON for 4 mins. Set the headlamps to OFF for 2 mins. Set the ignition to OFF Test the battery voltage

Maintenance time intervals should always be obeyed, even with low service mileages, to keep the vehicle at the best performance and condition.



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO. 24539	ADVISOR ARMAND	TAG NO. 29 855	INVOICE DATE 01/07/16	INVOICE NO. ASCS66445
	LABOR RATE 169.00	LICENSE NO.	COLOR LIGHTNING S	STOCK NO.
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/2DR CPE	MILEAGE 7,107	DELIVERY DATE	DELIVERY MILE
	VEHICLE I.D. NO. SCFAB06D49GE00855		WARRANTY EXP. DATE	PRODUCTION DATE
	F.T.E. NO.	P.O. NO.	R.O. DATE 01/06/16	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS		

MO: 8109

JOB# 1 CHARGES

LABOR

J# 1 30ASZ MANUAL TRANS CONCERN HOURS: 1.50 TECH(S): 96 253.50

CLIENT STATES THE CAR IS HARD TO SHIFT.
SHIFTER ADJUSTED TOO FAR FORWARD.
CONFIRMED ISSUE AND FOUND IT THE CAR SOMETIMES POPPED OUT
OF GEAR IN REVERSE, FIRST, 3RD AND 6TH. REMOVED CENTER
CONSOLE AND SHIFTER/COVER. REMOVED SHIFTER CABLE FROM TRANS
AND RELEASE SETTING SO IT HAD FREE MOVEMENT. INSTALLED
NEUTRAL SETTING TOOL THEN RECONNECTED SHIFTER CABLE IN THE
SET PLACE. RESET HOLD SETTING ON CABLE. REASSEMBLED SHIFTER
CONSOLE AND CENTER CONSOLE. SHIFTER NOW SITS EVENLY AND
ALL GEARS HAVE POSITIVE ENGAGEMENT. ROAD TESTED CAR.
AL OK.

JOB# 1 TOTALS LABOR 253.50

JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL 253.50

TOTALS

* [] CASH [] CHECK CK NO. [] *
* [] VISA [] MASTERCARD [] DISCOVER *
* [] AMER XPRESS [] OTHER [] CHARGE *
* DATE PAID CASHIER *

TOTAL LABOR.... 253.50
TOTAL PARTS.... 0.00
TOTAL SUBLET... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC 0.00
TOTAL TAX..... 16.10

TOTAL INVOICE \$ 269.60

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere
in the Continental US.
- Complete body shop

All these services are available
for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

Aston Martin Vehicle Maintenance Check Sheet
Always use body interior and exterior protection and the correct grades of lubricants and fluids. Tick the box in column "C" when the check is complete and tick in column "A" if corrective work is necessary.

FULLY CLEAN THE VEHICLE AND THE WORK AREA.

Owner: [REDACTED]

Vehicle Reg. No.: [REDACTED]

Model/Derivative: DB5

VIN: E00895

Date: 3/3/14

Key No.:

Odometer (km/mis): 5609

Dealer Job/Invoice No.: 54880

12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km		
x	x	Pre-Maintenance	
x	x	Install the vehicle protection kit and wing covers	
x	x	Do a check of the Campaign Status	
x	x	Fluid, Filters and Inspect for Leaks	
x	x	Examine the engine for oil leaks	
x	x	Renew the engine oil (use the correct specification)	
x	x	Renew the engine oil filter	
x	x	Renew the air cleaner element(s) (V12 Engines)	
Every 3 years or 30,000 mls (48,000 km)		Renew the air cleaner element(s) (V8 Engines)	
x		Examine the transmission and final drive for condition and leaks. Fill if necessary	
Every 6 years 60,000 mls 96,000 km	Every 10 years 100,000 mls 160,000 km	Do a check of the manual transaxle oil level. Fill if necessary	
Every 4 years or 40,000 mls (64,000 km)		Renew the manual transaxle oil and clean the filter	
Every 4 years or 40,000 mls (64,000 km)		Renew the automatic differential oil and clean the filter	
x	x	Examine the engine cooling and occupant heating system for condition and leaks. Fill if necessary	
Every 5 years or 50,000 mls (80,000 km)		Renew the engine coolant - 50/50 concentration	
x	x	Examine the condition and attachment of the fuel system, hoses, pipes and unions for leaks	
Every 12 months		Renew the brake/clutch fluid (use the correct specification) (V12 engines)	
Every 24 months		Renew the brake/clutch fluid (use the correct specification) (V8 engines)	
x	x	Examine the brake/clutch fluid level. Fill if necessary	
x	x	Examine the condition and attachment of the power steering system, hose, pipes and unions	
x	x	Examine the power steering fluid level and fill if necessary	
x	x	Examine the condition and attachment of the brake system, hoses, pipes and unions	
x	x	Examine the condition of the suspension dampers for leaks	
x	x	Examine the condition of the exhaust system for leaks	
x	x	Examine the level of the the windscreen and headlamp washer reservoir. Fill if necessary	
x	x	Do a check of the exhaust bypass valve operation at 800/3000 rpm	

Model/Applicability:
V8 and V12 Vantage, Vantage S, DB9, DBS, Rapide, Virage. For all other models please use the applicable Maintenance Check Sheet.

Note: For maximum customer satisfaction, we recommend that you do a road test before the maintenance is done, and again when the work is complete.

x	x	Examine the condition and attachment of the air conditioning system, hoses, pipes and unions. Use UV to do a check for leaks	
-	x	Renew the pollen filter	
12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km	Mechanical Function Check	
x	x	Examine the condition, attachment, correct operation and lubricate all door locks, latches, hinges and joints.	
x	x	Examine the condition, attachment, correct operation and lubricate the bonnet catch.	
x	x	Examine the condition, attachment, correct operation and lubricate the secondary bonnet catch(es).	
x	x	Examine the condition and tension of the accessory drive belt. Adjust or replace if necessary	
x	x	Examine the cooling pack radiator, condenser and transmission cooler for blockage and unwanted material. Clean if necessary	
x	x	Examine the condition and attachment of the cooling system hoses	
x	x	Examine the condition and attachment of the air conditioning hoses	
Every 4 Years or 40,000 miles (64,000 km)		Clean the throttle butterflies (V12 only)	
x	x	Examine the condition and attachment of the wiper blades. Replace if necessary	
x	x	Examine the condition and operation of all seat belts and buckles	
x	x	Examine the condition and attachment of the rear view mirror	
x	x	Examine the condition and attachment of the handbrake and the handbrake pads	
x	x	Examine the condition, attachment and adjustment of the handbrake cables. Adjust if necessary	
x	x	Examine the condition of the brake pads, brake discs and calipers. At 60% wear, replace the brake pads and pad wear sensors. For CCM Brakes, at every 3rd pad change, clean, dry, weigh and examine the condition of the brake discs	
x	x	Examine the condition and attachment of front brake disc shields for fatigue, cracks and the clearance from the discs	
x	x	Examine the condition and attachment of all suspension, ball joints, gaiters, bushes and fittings	
-	x	Examine the condition and attachment of the driveshafts	
x	x	Examine the condition and attachment of the exhaust system, mountings and heatshields	
-	x	Examine the condition and attachment of the wheel arch liners and the underbody protection	

Maintenance time intervals should always be obeyed, even with low service mileages, to keep the vehicle at the best performance and condition.

Aston Martin Vehicle Maintenance Check Sheet

12 Months
10,000 mls
16,000 km

24 months
20,000 mls
32,000 km

Electrical Function Test

Every 70,000 mls (112,000 km)	12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km		
x	x		Renew the spark plugs	/
x	x		Measure and record the battery voltage	/
x	x		Examine the condition and attachment of the battery connections. Adjust if necessary	/
x	x		Do a functional test of the battery disconnect switch	/
x	x		Examine the condition and attachment of all lamp units	/
x	x		Do a check of the headlamp alignment. Adjust if necessary	/
x	x		Do a functional test of all of the lights and the auto-sense function	/
x	x		Do a functional test of all warning indicators	/
x	x		Do a functional test of the audible warnings and security system	/
x	x		Do a functional test of the horns	/
x	x		Do a functional test of the windscreen wipers and auto-sense function	/
x	x		Do a functional test of the windscreen and headlamp washers	/
x	x		Examine the condition and attachment of the door mirrors	/
x	x		Do a functional test of the fold-back door mirrors	/
x	x		Do a functional test of the electrically operated windows	/
x	x		Do a functional check of the service indicator. Reset the indicator	/
x	x		Renew the batteries in the remote key fobs	/
x	x		Renew the tracker tags (where applicable)	/

Anti Corrosion Check

x	x	Examine the body panels and under body for corrosion. Work from the inside out (do not include stone chips)	/
---	---	---	---

Comments

Technician

Name

Dealer Stamp

Sign and Date

Maintenance time intervals should always be obeyed, even with low service mileages, to keep the vehicle at the best performance and condition.

12 Months
10,000 mls
16,000 km

24 months
20,000 mls
32,000 km

Wheels and Tyres Check

12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km		
x	x	Make sure that the tyres are the correct size, type and orientation	/
x	x	Measure and record the tyre tread depth	/
x	x	Examine the tyres for uneven or excessive wear or damage	/
x	x	Measure and if necessary, adjust the tyre pressures	/
x	x	Do a torque check of the road wheel nuts	/
x	x	Examine the road wheel rims for inside or outside damage. Record all damage	/
x	x	Make sure that the colour coded tyre pressure monitor system valve caps are on the correct wheels (if applicable)	/
x	x	Do a functional test of the tyre pressure sensors	/
x	x	Do a check of the date of the tyre inflation kit	/


Final Checks

12 Months 10,000 mls 16,000 km	24 months 20,000 mls 32,000 km		
x	x	Degrease the windscreen	/
x	x	Do a road test	/
x	x	Do a functional test of the ABS and the traction control operation	/
x	x	Make sure that the drain for the fuel filler bowl is clear	/
x	x	Do a functional test of the adaptive damping system	/

Tyre Wear Report

	Outer	Centre	Inner	Outer	Centre	Inner
	Across Tyre			Across Tyre		
	Left Front (mm)			Right Front (mm)		
CW Rotation						
Valve						
90°						
120°						
270°						
Tyre Pressure						
CW Rotation						
Valve						
90°						
120°						
270°						
Tyre Pressure						

Fuel Level	Open Circuit Battery Voltage	To remove the surface charge
Record the fuel level when the vehicle arrives at your Dealership. Always fill the fuel tank before you return the vehicle (chargeable)	12.7 Volts	Set the Ignition to ON Set the headlamps to ON for 4 mins. Set the headlamps to OFF for 2 mins. Set the Ignition to OFF Test the battery voltage





MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO. 24539	ADVISOR ARMAND	TAG NO. 29 0855	INVOICE DATE 02/04/15	INVOICE NO. ASCS60009
	LABOR RATE 169.00	LICENSE NO.	MILEAGE 7,093	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/2DR CPE		DELIVERY DATE	DELIVERY MILES
	VEHICLE I.D. NO. S C F A B 0 6 D 4 9 G E 0 0 8 5 5		WARRANTY EXP. DATE	PRODUCTION DATE
	F.T.E. NO.	P.O. NO.	R.O. DATE 01/23/15	
RECEIVED PHONE	BUSINESS PHONE	COMMENTS		

MO: 7107

JOB# 1 CHARGES-----
LABOR-----
1 00ASZ SERVICE HOURS: TECH(S):709 0.00
CLIENT STATES CHECK THE VEHICLE FOR THE YEARLY SERVICE.
CHECKED VEHICLE OVER FOR SERVICE. WORK DECLINED AT THIS
TIME.

JOB# 1 TOTALS-----
JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL 0.00
JOB# 2 CHARGES-----

LABOR-----
2 57ASZ CAMPAIGN HOURS: 0.70 TECH(S):709 WARRANTY
CLIENT STATES CHECK THE VEHICLE FOR CAMPAIGN RA-01-0019
SEAT HEAT
PERFORMED CAMPAIGN RA-01-0019. INSTALLED SEAT HEATER
HARNES. CONFIRMED BOTH SEAT HEATERS FUNCTIONING PROPERLY.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	1		FG43-632B22-AA	SEAT HEATER KIT		
					TOTAL - PARTS	0.00

JOB# 2 TOTALS-----
JOB# 2 JOURNAL PREFIX ASCS JOB# 2 TOTAL 0.00
JOB# 3 CHARGES-----

LABOR-----
3 10ASZ01 DRIVEABILITY CONCERN HOURS: 2.05 TECH(S):709 346.45
CLIENT STATES THE CAR IS HARD TO SHIFT AND THE CLUTCH SEEMS
TO BE SLIPPING.
ROAD TESTED VEHICLE SEVERAL TIMES AND COULD NOT DUPLICATE
CLIENTS CONCERN. CLUTCH OPERATION FEELS NORMAL WITH NO
SLIPPAGE. RECOMMENDED MANUAL TRANSMISSION FLUID SERVICE DUE
TO AGE OF VEHICLE. DRAINED AND REFILLED TRANSMISSION WITH
PROPER FLUID AT PROPER LEVEL AND TEMPERATURE. ROAD TESTED
AND ALL OK.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	5		6G33-75106-AA/S	TRANSMISSION OIL	56.55	282.75
	2		4G43-27-10245-PK	COPPER WASHER	8.02	16.04
					TOTAL - PARTS	298.79

JOB# 3 TOTALS-----
LABOR 346.45
PARTS 298.79
JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 645.24
JOB# 4 CHARGES-----

LABOR-----
4 70ASZRS ROADSIDE ASSISTANCE HOURS: TECH(S):29 WARRANTY
CLIENT STATES FLATBED THE VEHICLE.

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere
in the Continental US.
- Complete body shop

**All these services are available
for all of your other vehicles.**

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO 24539	ADVISOR ARMAND	TAG NO 29 0855	INVOICE DATE 02/04/15	INVOICE NO ASCS60009
	LABOR RATE 169.00	LICENSE NO.	MILEAGE 7,093	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/2DR CPE			STOCK NO.
	VEHICLE ID. NO. SCFAB06D49GE00855			DELIVERY DATE
	F.T.E. NO.	P.O. NO.	WARRANTY EXP. DATE 01/23/15	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS		

MO: 7107

ROAD SIDE IN AS REQUESTED. FLATBED RETURNED AS REQUESTED.

SUBLET	PO#	VEND	INV#	INV. DATE	DESCRIPTION	WARRANTY
	76158	22690		01/23/15	FB JANISZWESKI TO MMC 1-22M	335.00
	76309			02/03/15	FB JANISEWSKI TO HOME 2-4M	335.00
TOTAL - SUBLET						335.00

JOB# 4 TOTALS----- SUBLET 335.00

JOB# 4 JOURNAL PREFIX ASCS JOB# 4 TOTAL 335.00

JOB# 5 CHARGES-----

LABOR-----
3# 5+20ASZ0002 COOLING SYS CONCERN HOURS: 2.00 TECH(S):709 338.00
PERFORM CLIENT APPROVED COOLANT SERVICE
DRAINED, FLUSHED AND REFILLED COOLING SYSTEM TWICE, FILLED
WITH NEW FLUID. RAN VEHICLE WHILE CHECKING FOR LEAKS,
THERMOSTAT AND COOLING FAN OPERATION. ALL OK.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	1		PKCOOLANT	COOLANT FLUSH	****	****
	1		32-86355	DRAIN PLUG	17.86	17.86
	1		2015	RADIATOR FLUSH	8.91	8.91
	4		00060	DIST WATER	5.42	21.68
	5		1R12-322665-AA-PK	1LTR OAT COOLANT	27.30	136.50
TOTAL - PARTS						184.95

JOB# 5 TOTALS----- LABOR 338.00
PARTS 184.95

JOB# 5 JOURNAL PREFIX ASCS JOB# 5 TOTAL 522.95

MISC	CODE	DESCRIPTION	CONTROL NO	PRICE
JOB # A	4FHAZ	HAZ MAT/SHOP SUPPLIES/MISC		15.00
TOTAL - MISC				15.00

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere in the Continental US.
- Complete body shop

All these services are available for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO. 24539	ADVISOR ARMAND	TAG NO. 29 0855	INVOICE DATE 02/04/15	INVOICE NO. ASCS60009
	LABOR RATE 169.00	LICENSE NO.	COLOR LIGHTNING S	STOCK NO.
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/2DR CPE	MILEAGE 7,093	DELIVERY DATE	DELIVERY MILES
	VEHICLE I.D. NO. S C F A B 0 6 D 4 9 G E 0 0 8 5 5	WARRANTY EXP DATE	PRODUCTION DATE	
	F.T.E. NO.	P.O. NO.	R.O. DATE 01/23/15	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS		

MO: 7107

TOTALS

 * [] CASH [] CHECK CK NO. [] *
 * [] VISA [] MASTERCARD [] DISCOVER *
 * [] AMER XPRESS [] OTHER [] CHARGE *
 * DATE PAID CASHIER *

TOTAL LABOR.... 684.45
 TOTAL PARTS.... 483.74
 TOTAL SUBLET... 335.00
 TOTAL G.O.G.... 0.00
 TOTAL MISC CHG. 15.00
 TOTAL MISC DISC 0.00
 TOTAL TAX..... 96.41

TOTAL INVOICE \$ 1614.60

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

MILLER MOTORCARS INC
 273 WEST PUTNAM AVE
 GREENWICH, CT 06830

02/04/2015
 Merchant ID
 Terminal ID
 178184760993

CREDIT CARD
 VISA SALE

CARD # XXXXXXXXXXXX6347
 INVOICE 0005
 Batch #: 000842
 Approval Code: 00237D
 Entry Method: Manual
 Mode: Online
 SALE AMOUNT \$1614.60

CUSTOMER COPY

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paintless dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere in the Continental US.
- Complete body shop

All these services are available for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO. 24539	ADVISOR ARMAND	TAB NO. 29	INVOICE DATE 03/04/14	INVOICE NO. ASCS54880
	LABOR RATE 159.00	LICENSE NO.	MILEAGE 5,609	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/2DR CPE			DELIVERY DATE
	VEHICLE I.D. NO. S C F A B 0 6 D 4 9 G E 0 0 8 5 5			DELIVERY MILES
	F.T.E. NO.			WARRANTY EXP. DATE
	P.O. NO.			PRODUCTION DATE
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS MO: 5618		

JOB# 1 CHARGES

LABOR
J# 1 00ASZ1YR ONE YEAR SERVICE HOURS: 7.75 TECH(S): 96 1232.25

CLIENT STATES CHECK THE VEHICLE FOR THE YEARLY SERVICE.
PERFORM CLIENT APPROVED ONE YEAR INTERVAL SERVICE
DISCOUNT 10% FOR WINTER SERVICE SPECIAL

PERFORMED ONE YEAR SERVICE AS PER ASTON MARTIN MAINTENANCE
SCHEDULE. RESET SERVICE INTERVAL LIGHT, CHECKED AND CHARGED
BATTERY, CHECKED AND CLEARED CODES, CLEANED, LUBED,
SERVICED BRAKE PADS WITH TUNAP PASTE FOR BRAKE NOISE,
ROAD TESTED AND RE-BED IN BRAKES, ALL OK.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT	PRICE
	1		PK38	1 YEAR SERVICE	****	****
	12		PY-112988-PA	1LITRE ENGINE OIL	11.10	133.20
			0W40 MOBIL 1			
	1		AG43-6714-AA-PK	V12 OIL FILTER	52.25	52.25
	1		1R12-08-10317-PK	O-RING	6.26	6.26
	1		4G43-04-10205-PK	OIL DRAIN PLUG	27.17	27.17
	1		700781-PK	BRAKE FLUID	34.71	34.71
	1		WSW	WSW SOLVENT	3.10	3.10
	1		508	BRAKECLEAN	2.87	2.87
	8		705065	TUNAP MP113 AERO	7.66	61.28
TOTAL - PARTS						320.84

MISC	CODE	DESCRIPTION	CONTROL NO
	TA10	TOTAL RO 10% ASTON	
TOTAL - MISC			-155.31

JOB# 1 TOTALS

LABOR 1232.25
PARTS 320.84
MISC -155.31

JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL 1397.78

JOB# 2 CHARGES

LABOR
J# 2 00ASZ10 EXTENDED WARRANTY HOURS: TECH(S): 96 0.00

CLIENT STATES CHECK THE VEHICLE FOR THE EXTENDED SERVICE
CONTRACT.
PERFORMED 140 MULTI POINT INSPECTION PRIOR TO ACCEPTANCE
OF SERVICE CONTRACT.

SUBLET	PO#	VEND	INV#	INV. DATE	DESCRIPTION
	67955			03/04/14	TWO YEAR PREMIUM 5-10
TOTAL - SUBLET					7242.00

JOB# 2 TOTALS

SUBLET 7242.00

JOB# 2 JOURNAL PREFIX ASCS JOB# 2 TOTAL 7242.00

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere
- In the Continental US.
- Complete body shop

All these services are available
for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO.	24539	ADVISOR	ARMAND	29	TAG NO.	0855	INVOICE DATE	03/04/14	INVOICE NO.	ASC554880
		LABOR RATE	159.00	LICENSE NO.		MILEAGE	5,609	COLOR	LIGHTNING S	STOCK NO.
		YEAR / MAKE / MODEL	09/ASTON MARTIN/DBS/2DR CPE				DELIVERY DATE		DELIVERY MILES	
		VEHICLE I.D. NO.	S C F A B 0 6 D 4 9 G E 0 0 8 5 5				WARRANTY EXP. DATE		PRODUCTION DATE	
		R.T.E. NO.		P.O. NO.			R.O. DATE	02/27/14		
RESIDENCE PHONE		BUSINESS PHONE		COMMENTS						

MO: 5618

JOB# 3 CHARGES

LABOR-----
J# 3 57ASZ CAMPAIGN HOURS: 0.45 TECH(S):96 WARRANTY
CLIENT STATES CHECK THE VEHICLE FOR CAMPAIGN RA-03-0017.
TIER D & H.
PERFORMED CAMPAIGN AS PER ASTON MARTIN SPEC. CHECKED
THROTTLE TRAVEL AND IT WAS AT 100%. REPLACED THROTTLE PEDAL
AS PER ASTON MARTIN REQUIREMENT.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	1		8D33-9N734-AC	THROTTLE PEDAL		0.00
					TOTAL - PARTS	0.00

JOB# 3 TOTALS-----
JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES

LABOR-----
J# 4 70ASZIFLAT INT FLATBED HOURS: 0.00 TECH(S):40 0.00
CLIENT STATES FLATBED THE VEHICLE.
MMC COVERS ONE WAY THIS TIME ONLY.
FLATBED AS REQUESTED

SUBLET	PO#	VEND	INV#	INV. DATE	DESCRIPTION	
	67828	18934		02/27/14	FB JANISZEWSKI TO MMC 2/27M	200.00
					TOTAL - SUBLET	200.00

JOB# 4 TOTALS-----
SUBLET 200.00
JOB# 4 JOURNAL PREFIX ASCS JOB# 4 TOTAL 200.00

MISC	CODE	DESCRIPTION	CONTROL NO	
JOB # A	4FHAZ	HAZ MAT/SHOP SUPPLIES/MISC		15.00
			TOTAL - MISC	15.00

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere in the Continental US.
- Complete body shop

All these services are available for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.



MILLER MOTORCARS

186 Magee Ave., Stamford, CT 06902
(203) 661-2555

CELL: 860-682-0700

CUSTOMER NO. 24539		ADVISOR ARMAND		29	TAG NO. 0855	INVOICE DATE 03/04/14	INVOICE NO. ASC554880
LABOR RATE 159.00		LICENSE NO.		MILEAGE 5,609		COLOR LIGHTNING S	STOCK NO.
YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/2DR CPE		VEHICLE I.D. NO. SCFAB06D49GE00855		DELIVERY DATE		DELIVERY MILES	
RESIDENCE PHONE		BUSINESS PHONE		WARRANTY EXP. DATE 02/27/14		PRODUCTION DATE	
COMMENTS		P.O. NO.		R.O. DATE		MO: 5618	

TOTALS		TOTAL LABOR.... 1232.25	
*****		TOTAL PARTS.... 320.84	
* [] CASH [] CHECK CK NO. [] *		TOTAL SUBLET.... 7442.00	
* [] VISA [] MASTERCARD [] DISCOVER *		TOTAL G.O.G.... 0.00	
* [] AMER XPRESS [] OTHER [] CHARGE *		TOTAL MISC CHG. 15.00	
*****		TOTAL MISC DISC -155.31	
DATE PAID CASHIER *		TOTAL TAX..... 572.14	
*****		TOTAL INVOICE \$ 9426.92	

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

OTHER AVAILABLE SERVICES

- Full detail of the car
- Horse power upgrades
- Vehicle styling enhancements
- Paint less dent removal
- Touch up and chip removal
- Lower front bumper repairs
- Damaged wheel repairs
- Custom wheel fabrication
- Window tinting
- Stereo system upgrades
- Satellite radio systems
- Radar detectors
- Laser diffusers
- Leather repair
- Clear protective film
- Car covers
- Upholstery products
- Apparel and accessories
- Transport of your vehicle anywhere in the Continental US.
- Complete body shop

All these services are available for all of your other vehicles.

DISCLAIMER OF WARRANTIES

The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

The Reynolds and Reynolds Company FORM 1000-CC235816 Q (07/13)



ASTON MARTIN

ASTON MARTIN MULTI-POINT INSPECTION CERTIFICATE

Always use Aston Martin body protection covers, interior vehicle protection materials and the correct grades of lubricants and fluids

VIN	SCFABC06D49GEO0855
Model	DBS
Date	3/11/14
Key no. (s)	
Reg. no.	
Body colour	Lightning Silver

Trim colour/piping/stitching	Black
Repair order no.	54880
Inspected by (print name)	Dan
Recorded mileage* (miles/km)	5609
Validated mileage	5618
Test due	

*The recorded mileage quoted is correct as shown on the odometer

Box C = Check Box, Box A = Adjust

CONDITION CHECK

		C	A
1	Bumper, front fog lamps and apron	✓	
2	Bonnet vents (where fitted)	✓	
3	Headlamp surrounds	✓	
4	Front wings, badges, finishers and vents	✓	
5	Aerial (where fitted)	✓	
6	'A', 'B' and 'C' post	✓	
7	Interior and door mirrors	✓	
8	Doors, frames, handles and shuts	✓	
9	Tread plates and sill finishers	✓	
10	Rear wings	✓	
11	Wheel arch liners / wheel arch under-seal	✓	
12	Boot lid, number plate brackets and badges	✓	
13	Boot shut and rear spoiler (where fitted)	✓	
14	Rear bumper/apron	✓	
15	Rear fog lamps	✓	
16	Exhaust finishers	✓	
17	Front/rear grille finishers	✓	

WHEELS

18	Alloy rim condition	✓	
19	Valve caps and tyre pressure sensors (TPMS)	✓	

CARPETS AND RUGS

20	Carpet/binding	✓	
21	Rugs/Overmats	✓	
22	Boot carpets	✓	

GLASS

23	Windscreens, door and side glass	✓	
24	Headlamps, side lamps, side markers, reflectors	✓	
25	Direction indicators, stop lamps, no. plate lamps	✓	

ENGINE BAY

26	Engine, inner wings, under-seal and bulkhead	✓	
27	Bonnet soundproofing and beautification panels	✓	

WOODWORK AND VENEERS

28	Fascia and console panels	✓	
29	Door cappings	✓	
30	Optional extras (where fitted)	✓	

LEATHER/ALCANTARA TRIM

31	Top roll	✓	
32	Seats	✓	

LEATHER/ALCANTARA TRIM cont.

		C	A
33	Knee bolsters	✓	
34	Steering wheel	✓	
35	Head lining, convertible hood and wind deflector (Volante/Roadster)	✓	
36	Sun visors and vanity mirrors	✓	
37	Door casings	✓	
38	Centre consoles and storage compartments	✓	
39	Parcel shelf and headrests	✓	
40	'A', 'B' and 'C' post trims	✓	

INTERNAL BRIGHTWARE

41	All metallic brightware/badges	✓	
----	--------------------------------	---	--

INSTRUMENTS AND SWITCHES

42	All fascia gauges and switches	✓	
43	Fuse boxes interior/engine bay/boot	✓	
44	ICE and console switches/sat. nav.	✓	

RUBBER COMPONENTS

45	Tyres, spare tyre, compressor, canisters	✓	
46	Door, boot and bonnet seals	✓	
47	Driver's pedal rubbers	✓	
48	Footrest (where fitted)	✓	

LEVELS AND LEAKS CHECK

49	Engine oil level between MIN and MAX	✓	
50	Transmission oil (auto/manual)	✓	
51	Rear axle oil, transaxle	✓	
52	Power steering fluid	✓	
53	Brake fluid	✓	
54	Clutch fluid	✓	
55	Engine coolant and specific gravity	✓	
56	Intercooler coolant and specific gravity (where fitted)	✓	
57	Windscreen washer fluid	✓	
58	Fuel system	✓	
59	Hydraulic roof fluid (Volante/Roadster)	✓	
60	A/C System leak check	✓	

MECHANICAL FUNCTION CHECK

61	Auto transmission/manual transmission	✓	
62	Gear selection	✓	
63	Clutch operation/start inhibit	✓	

MECHANICAL FUNCTION CHECK cont.

		C	A
64	Throttle pedal operation, full throttle	✓	
65	Brake pedal operation	✓	
66	Parking brake operation	✓	
67	Steering column operation/adjustment	✓	
68	Bonnet release and catch	✓	
69	Door operation and locks	✓	
70	Storage compartments	✓	
71	Rear view mirror dip	✓	
72	Wheels and tyres	✓	
73	Road wheel nut torque	✓	
74	Front wheel tracking. If incorrect, use the Hunter alignment equipment to do a check of the four-wheel alignment	✓	
75	Steering wheel alignment (static)	✓	
76	Drive line nut and bolt check	✓	
77	Exhaust system	✓	

ELECTRICAL CHECKS

78	Battery condition**	✓	
79	Heated front and rear screens	✓	
80	A/C Controls	✓	
81	Vehicle security system and remote controls	✓	
82	Gauges and warning lights	✓	
83	ICE function	✓	
84	Speakers and aerial	✓	
85	Side lamps, parking lamps and number plate lamps	✓	
86	Headlamps (main and dip)	✓	
87	Fog lights - front and rear (where fitted)	✓	
88	Direction indicators, hazard warning lights	✓	
89	Instrument illumination and dimmer	✓	
90	A/C Panel illumination	✓	
91	Automatic PRND illumination (where applicable)	✓	
92	Horns	✓	
93	Door, boot, and bonnet courtesy lamps and interior, map and sun-visor lights	✓	
94	Cigar lighter	✓	
95	Seat functions and heater adjustments	✓	
96	Door mirror adjustments	✓	
97	Clock (reset if necessary)	✓	
98	Central locking system (deadlocking)	✓	
99	Fuel filler flap lock operation	✓	
100	Seat belts and warning system	✓	

ROAD TEST/PERFORMANCE

101	Engine -full throttle/idle	✓	
102	Clutch	✓	
103	Manual transmission	✓	
104	Automatic transmission and kick-down	✓	
105	Rear axle differential and transaxle	✓	
106	Steering	✓	
107	Brakes/ABS traction control (where fitted)	✓	
108	Wheel balance	✓	
109	Dampers	✓	
110	Cruise control	✓	

** Remove surface charge before recording charge

ROAD TEST/PERFORMANCE cont.

		C	A
111	HVAC performance	✓	
112	Instruments operation	✓	
113	Seat belt and buckle operation	✓	
114	Steering wheel alignment (dynamic)	✓	
115	Selection PRND functions (start inhibit)	✓	
116	Exhaust system leaks, bypass valves	✓	

POST ROAD TEST

117	Transmission fluid level	✓	
118	Drive belt tensions	✓	
119	Fuel/brake pipe security	✓	
120	Fuel/fluid leaks	✓	
121	Cooling system hose security	✓	

TYRE CONDITION (4mm inc. wear indicator)

		Inside	Centre	Outside	Pressure
122	Left front	5 mm	mm	7 mm	36 psi
123	Right front	5 mm	mm	2 mm	36 psi
124	Left rear	4 mm	mm	mm	38 psi
125	Right rear	4 mm	mm	mm	38 psi
126	Spare	mm	mm	mm	psi
127	Tyres are correct type, manufacturer and sizes				

BRAKE PAD INSPECTION (min 5mm of friction material)

128	LF	129	RF	130	LR	131	RR
9 mm	9 mm	9 mm	9 mm	9 mm	9 mm	9 mm	9 mm

VEHICLE HISTORY/MAINTENANCE

132	Warranty history, Campaigns, Service Actions	✓	
133	Owners guide, Service and Warranty booklets present	✓	
134	Service history up to date - last recorded less than 9 months ago, or within 3000 miles	✓	

FINAL INSPECTION

135	Check function of all keys / ECU (batteries)	✓	
136	Valet vehicle	✓	
137	Degrease windscreen	✓	
138	Fit carpets and accessory mat	✓	
139	Remove interior protection	✓	
140	Check tools, compressor and spares	✓	

COMMENTS

Service Manager's Signature:

Print Name:

Franchised Dealer Stamp:

Miller Motorcars Aston Martin Long Island



ASTON MARTIN

Service Location

85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11576
Phone (516) 478-4326
Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6721

INVOICE NO. 2446	ANMOOR SIMON RODD	10	TAG NO. 1753	INVOICE DATE 10/08/12	INVOICE NO. ASCS16279
LABOR DATE			LICENSE NO.	MILEAGE 3,760	COLOR LIGHTNING S
YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS			DELIVERY DATE 01/17/09		DELIVERY MILES 509
VEHICLE ID NO. S C F A B 0 6 D 4 9 G E 0 0 8 5 5			SELLING DEALER NO. AM OF LI		PRODUCTION DATE
F.T.E. NO.			P.O. NO.		R.G. DATE 09/28/12
COMMENTS					
MO: 3767					

LABOR: JOB# 1 00ASZ SERVICE HOURS: TECH(S):25 750.58

CUSTOMER REQUESTS NEXT ANNUAL SERVICE. CHECK VEHICLE HISTORY AND ADVISE. VEHICLE IS DUE FOR A 3RD ANNUAL SERVICE. PERFORMED A 3 YEAR SERVICE, DRAINED ENGINE OIL AND REPLACED OIL FILTER, CHECKED ALL FLUIDS, ADJUSTED TIRE PRESSURES, RECORDED TREAD DEPTH, BLEED BRAKE SYSTEM AND TOPPED UP FLUID LEVEL, TORQUED ALL WHEELS, CHECKED TORQUE ON REAR AXLES, LUBED ALL LATCHES, CHECKED ALL LIGHTS, CHECKED SUSPENSION, CHECKED EXHAUST, CHECKED BRAKE LININGS, CHECKED VEHICLE FOR LEAKS, ROAD TESTED VEHICLE, STAMPED OWNERS MANUAL.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
	1		PKV123YR	3YR SERVICE V12	****	****
	1		4G43-04 10205	DRAIN PLUG	23.15	23.15
	1		700781	CAS SUPER DOT 4	28.16	28.16
	2		08180	BRAKE CLEANER	4.99	9.98
	1		AG43-6714-AA	OIL FILTER	46.43	46.43
	13		0W-40	SYNTHETIC OIL	11.20	145.60
	1		W/W	WASHER FLUID	4.53	4.53
	1		4G43-40-10137	TYRE INFLATOR REFI	56.57	56.57
				TOTAL PARTS	314.42	

JOB# 1 TOTALS: LABOR 750.58 PARTS 314.42

JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL 1065.00

JOB# 2 CHARGES:

LABOR: JOB# 2 61ASZ

EXTERIOR TRIM HOURS: TECH(S):25 0.00
CUSTOMER STATES CARBON FIBER MIRROR STALK ON DRIVER'S SIDE IS STARTING TO BUBBLE OR LIFTING OFF FROM THE CARBON FIBER ITSELF. VEHICLE NEEDS COMPLETE MIRROR ASSEMBLY, UNREPAIRABLE. CUSTOMER DECIDED TO LEAVE THE ISSUE ALONE AT THIS TIME.

JOB# 2 TOTALS:

JOB# 2 JOURNAL PREFIX ASCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES:

LABOR: JOB# 3 61ASZ20

EXT MIRROR HOURS: 0.50 TECH(S):25 77.50
CUSTOMER STATES PASSENGER'S SIDE OUTSIDE MIRROR PAINTED COVER NEEDS TO BE REPLACED. SUPLET PAINTING OF THE MIRROR COVER TO FLOWER HILL AUTO BODY. SUPLET PAINT PROTECTION REPLACEMENT TO EAGLE GUARD REMOVED AND REPLACED BROKEN MIRROR COVER, PASSENGER SIDE.

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

ALL PARTS ARE NEW OR FACTORY REBUILT, PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY.

PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES: A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR.

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK PERFORMED AND RECEIPT OF COPY OF THEREOF.

X
ALL WORK C.O.D.

Miller Motorcars Aston Martin Long Island



ASTON MARTIN

Service Location

85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location

1080 Northern Blvd. - Roslyn, NY 11576
Phone (516) 478-4326
Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

CUSTOMER NO 2446	ADVISOR SIMON RODD	TAX NO. 10 1753	INVOICE DATE 10/08/12	INVOICE NO. ASCS16279
	FACTOR RATE	LICENSE NO.	MILEAGE 3,760	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS		DELIVERY DATE 01/17/09	STOCK NO.
	VEHICLE ID NO. SCFAB06D49GE00855		SELLING DEALER NO. AM OF LI	DELIVERY MILES 509
	E.T.E NO.	R.G. NO.	R.D. DATE 09/28/12	PRODUCTION DATE
COMMENTS				MO: 3767

FAIRTS	QTY	FP NUMBER	DESCRIPTION	UNIT	PRICE
	1	6643-37-10129	MIRROR CAP-RH		80.94
			TOTAL - PARTS		80.94
SUBLET	PO#	VEND INV#	INV. DATE DESCRIPTION		
	20050		10/08/12 PAINT MIRROR COVER PASS SID		65.00
	20051		10/08/12 PAINT PROT. PASS MIRROR COV		60.00
			TOTAL - SUBLET		125.00
JOB# 3 TOTALS					
			LABOR		77.50
			PARTS		80.94
			SUBLET		125.00
JOB# 4 CHARGES			JOB# 3 JOURNAL PREFIX ASCS	JOB# 3 TOTAL	283.44
LABOR					
J# 4 61ASZ11			WEATHERSTRIPS HOURS: 0.20 TECH(S):25		31.00
			CUSTOMER STATES THE CLOTH INSULATION ATTACHED TO THE UNDERSURFACE OF THE HOOD IS BEING WORN AWAY. HOOD INSULATION IS HANGING DOWN SLIGHTLY. TRIMMED AND ADJUSTED HOOD INSULATION TO CORRECT.		
JOB# 4 TOTALS					
			LABOR		31.00
			JOB# 4 JOURNAL PREFIX ASCS	JOB# 4 TOTAL	31.00
JOB# 5 CHARGES					
LABOR					
J# 5 61ASZ01			EXT TRIM CONCERN HOURS: TECH(S):25		0.00
			CUSTOMER STATES THE CLEAR BRA IS PEELING AWAY ON THE DRIVER'S SIDE FRONT BUMPER. TRIMMED CLEAR BRA TO CORRECT ISSUE.		
JOB# 5 TOTALS					
			JOB# 5 JOURNAL PREFIX ASCS	JOB# 5 TOTAL	0.00
JOB# 6 CHARGES					
LABOR					
J# 6 70ASZ05			TOWING HOURS: TECH(S):25		0.00
			CUSTOMER REQUESTS FLATBED SERVICE TO AND FROM SHOP.		
SUBLET	PO#	VEND INV#	INV. DATE DESCRIPTION		
	20052		10/08/12 TOWING CO-PAY FROM MOORESTO		200.00
			TOTAL - SUBLET		200.00
JOB# 6 TOTALS					
			SUBLET		200.00
			JOB# 6 JOURNAL PREFIX ASCS	JOB# 6 TOTAL	200.00

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. ALL PARTS ARE NEW OR FACTORY REBUILT, PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY. PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES: A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR _____.

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING
YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK
PERFORMED AND RECEIPT OF COPY OF THEREOF.

X ALL WORK C.O.D.

Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050

Phone (516) 478-4328

Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11576

Phone (516) 478-4326

Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

INVOICE NO. 2446	ADVISOR SIMON RODD	TAG NO. 10 1753	INVOICE DATE 10/08/12	INVOICE NO. ASCS16279
	LABOR RATE	LICENSE NO.	MILEAGE 3,760	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS		DELIVERY DATE 01/17/09	DELIVERY MILES 509
	VEHICLE ID NO. SCFAB06D49GE00855		SELLING DEALER NO. AM OF LI	PRODUCTION DATE
	F.T.E. NO.	P.O. NO.	R.O. DATE 09/28/12	
COMMENTS				MO: 3767

MISC. CODE	DESCRIPTION	CONTROL NO.	
000 # A	DHW HAZARDOUS WASTE		8.59
TOTAL - MISC			8.59
TOTALS-----			

* [] CASH [] CHECK CK NO. [] *			
* [] VISA [] MASTERCARD [] DISCOVER *			
* [] AMER XPRESS [] OTHER [] CHARGE *			

TOTAL LABOR....			859.08
TOTAL PARTS....			395.36
TOTAL SUBLET....			325.00
TOTAL G.O.G....			0.00
TOTAL MISC CHG....			8.59
TOTAL MISC DISC....			0.00
TOTAL TAX.....			136.97
TOTAL INVOICE \$			1725.00

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. ALL PARTS ARE NEW OR FACTORY REBUILT, PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY. PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES: A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR _____.

N.Y.S. Repair Shop Registration No. R-7099622

Thank You FOR BRINGING YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK PERFORMED AND RECEIPT OF COPY OF THEREOF

X ALL WORK C.O.D.



Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050

Phone (516) 478-4328

Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11576

Phone (516) 478-4326

Fax (516) 478-4327



CELL: 856-266-6727

CUSTOMER NO	2446	NAME	PETER RODNEY	AGE	20	TRADE NO	1706	INVOICE DATE	10/28/11	INVOICE NO	ASCS15619
		LABOR RATE		LICENSE NO		MILEAGE	2,630	COLOR	LIGHTNING S	STOCK NO	
		YEAR / MAKE / MODEL	09 / ASTON MARTIN / DBS / DBS				DELIVERY DATE	01/17/09	DELIVERY MILES	509	
		VEHICLE ID NO	S C F A B 0 6 D 4 9 G E 0 0 8 5 5				SELLING DEALER NO	AM OF LI	PRODUCTION DATE		
		ETC NO		P.O. NO		R.O. DATE	10/21/11				
COMMENTS											MO: 2760

JOB# 1 CHARGES

LABOR					1550.00	
J# 1 00ASZ SERVICE HOURS: 10.00 TECH(S):08						
CUSTOMER REQUESTS THE 2 YEAR ANNUAL SERVICE						
TWO YEARS SERVICE WAS PERFORMED. SERVICE HANDBOOK WAS						
FILLED OUT AND STAMPED.						
PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE		
	1	PK2YRD89	2 YR SERVICE DB9	****	****	
	1	4G43-04-10205	DRAIN PLUG	22.37	22.37	
	2	4G43-27-10245	COPPER WASHER	3.44	6.88	
	1	4G43-27-10491	O-RING 2.62	2.62	2.62	
	1	700781	CAS SUPER DOT 4	27.19	27.19	
	2	08180	BRAKE CLEANER	4.99	9.98	
	1	4G43-17528-CA	WIPER	45.23	45.23	
	1	9G43-178437-AA	WIPER	39.80	39.80	
	2	JLM-20972-3	ANTIFREEZE	59.95	119.90	
	1	AG43-6714-AA	OIL FILTER	44.34	44.34	
	1	4G43-9601-AB	AIR CLEANER	101.14	202.28	
	1	4G43-13ZE1-AA-PK	FILTER-POLLEN	91.58	91.58	
	13	0W-40	SYNTHETIC OIL	11.20	145.60	
	2	DSTL	DISTILLED WATER	2.59	5.18	
	1	W/W	WASHER FLUID	4.53	4.53	
	5	6G33-75106-AA/S	OIL-MAN TRANS 1LTR	62.26	311.30	
	4	IR12-36-10555	VALVE DUST CAP	1.22	4.88	
				TOTAL - PARTS	1083.66	

SUBLET	PG#	VEND	INV#	INV DATE	DESCRIPTION	
	19608	2224		10/28/11	PICKUP AND DELIVER	
					TOTAL - SUBLET	INTERNAL 0.00

G.O.G. & SUPPLIES						
1.0 GAS	@	20.000	/UNIT		20.00	
					TOTAL - GOG	20.00

MISC	CODE	DESCRIPTION	CONTROL NO	
	LD2	10% LABOR DISCOUNT		155.00
	PD3	15% PARTS DISCOUNT		-162.55
				TOTAL - MISC
				-317.55

JOB# 1 TOTALS					
	LABOR			1550.00	
	PARTS			1083.66	
	G.O.G.			20.00	
	MISC			-317.55	

JOB# 2 CHARGES	JOB# 1 JOURNAL PREFIX	ASCS	JOB# 1 TOTAL	2336.11
----------------	-----------------------	------	--------------	---------

LABOR					0.00	
J# 2 00ASX EXTENDED SERVICE HOURS: 0.00 TECH(S):08						
EXTENDED SERVICE CONTRACT OFFER						
CUSTOMER REQUESTS THE 2 YEAR ESC						
ESC OFFER						

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

ALL PARTS ARE NEW OR FACTORY REBUILT. PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY.

PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES: A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING
YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK
PERFORMED AND RECEIPT OF COPY OF THEREOF.

X
ALL WORK C.O.D.

Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11576
Phone (516) 478-4326
Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

2446		ADVISED BY PETER RODNEY	TAG NO. 20 1706	INVOICE DATE 10/28/11	INVOICE NO. ASCS15619
		LABOR RATE	1.00 PER HOUR	2,630	COLOR LIGHTNING S
		YEAR MAKE MODEL 09/ASTON MARTIN/DBS/DBS	DELIVERY DATE 01/17/09	DELIVERY MILES 509	
		VEHICLE ID NO. S C F A B 0 6 D 4 9 G E 0 0 8 5 5	SELLING DEALER NO. AM OF LI	PRODUCTION DATE	
		P.T.E. NO.	P.O. NO.	R.O. DATE 10/21/11	
COMMENTS					MO: 2760
CUSTOMER APPROVED THE ESC. PERFORMED 140 POINT INSPECTION. CAR MEETS ESC CRITERIA.					
SUBLET	PO#	VEND	INV#	INV. DATE	DESCRIPTION
	19605		15619	10/27/11	2 YEAR ESC E00855
TOTAL					SUBLET 6500.00
JOB# 2 TOTALS					SUBLET 6500.00
JOB# 2 JOURNAL PREFIX ASCS					JOB# 2 TOTAL 6500.00
JOB# 3 CHARGES					
LABOR	JOB# 3 51ASZ BODY ELECTRICAL HOURS: TECH(S):08 0.00				
CUSTOMER FEELS HE HAS TO BE RIGHT ON TOP OF THE DOOR FOR THE REMOTES TO UNLOCK THE CAR. CHECK THE RANGE OF OPERATION. CHECKED RANGE OF REMOTE AND FOUND TO BE OPERATING AS DESIGNED. TESTED REMOTE FROM RIGHT NEXT TO VEHICLE AND FOUND TO BE OKAY. MOVED 5 FEET AWAY AND FOUND TO BE OPERATING OKAY. MOVED 10 FEET AWAY AND FOUND TO BE OPERATING OKAY. TRIED AGAIN AT 15 FEET FOUND TO BE OKAY. TEST A KNOWN GOOD VEHICLE AND FOUND THAT THE VEHICLE PRODUCED THE SAME RESULTS.					
JOB# 3 TOTALS					JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00
JOB# 4 CHARGES					
LABOR	JOB# 4 10ASZ DRIVEABILITY HOURS: TECH(S):08 0.00				
CUSTOMER STATES THE STEERING WHEEL SHAKES AT 60-70 MPH AT 70 MPH IT STOPS VIBRATING. RECOMMEND TO REPLACE BOTH FRONT WHEELS AND TIRES. TESTED AND FOUND THAT THE TWO FRONT RIMS ARE BENT. CUSTOMER WAS ADVISED.					
JOB# 4 TOTALS					JOB# 4 JOURNAL PREFIX ASCS JOB# 4 TOTAL 0.00
JOB# 5 CHARGES					
LABOR	JOB# 5 50ASZ08 CONSOLE HOURS: TECH(S):08 0.00				
CUSTOMER STATES THE ALUMINUM RING AROUND THE SHIFTER BOOT IS STARTING TO PIT. CHECKED OVER THE BASE RING ON THE SHIFTER BOOT. WAS UNABLE TO FIND ANY SIGNS OF PITTING. FOUND SEVERAL DIRT MARKS THAT WAS CLEANED AND A CHIP UNDERNEATH THE TRUNK RELEASE SWITCH.					
JOB# 5 TOTALS					JOB# 5 JOURNAL PREFIX ASCS JOB# 5 TOTAL 0.00
ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. ALL PARTS ARE NEW OR FACTORY REBUILT, PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY. PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES: A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR _____. N.Y.S. Repair Shop Registration No. R-7099622 Thank You FOR BRINGING YOUR CAR TO US FOR SERVICE. I ACKNOWLEDGE AND PRODUCT EXTRA WORK PERFORMED AND RECEIPT OF COPY OF THEREOF. X ALL WORK D.O.D.					

Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050

Phone (516) 478-4328

Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11578

Phone (516) 478-4326

Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

INVOICE NO. 2446	ADVISOR PETER RODNEY	TAB NO. 20	INVOICE DATE 10/28/11	INVOICE NO. ASCS15619
	LABOR RATE	LICENSE NO.	MILEAGE 2,630	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS		DELIVERY DATE 01/17/09	DELIVERY MILES 509
	VEHICLE I.D. NO. SCFAB06D49GE00855		SELLING DEALER NO. AM OF LI	PRODUCTION DATE
	P.T.E. NO.	P.O. NO.	R.O. DATE 10/21/11	
COMMENTS				MO: 2760

TOTALS

 * [] CASH [] CHECK CK NO. [] *
 * [] VISA [] MASTERCARD [] DISCOVER *
 * [] AMER XPRESS [] OTHER [] CHARGE *

TOTAL LABOR.... 1550.00
 TOTAL PARTS.... 1083.66
 TOTAL SUBLET... 6500.00
 TOTAL G.O.G.... 20.00
 TOTAL MISC CHG. 0.00
 TOTAL MISC DISC -317.55
 TOTAL TAX..... 774.41
TOTAL INVOICE \$ 9610.52

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

ALL PARTS ARE NEW OR FACTORY REBUILT. PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY.

PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES. A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR _____.

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK PERFORMED AND RECEIPT OF COPY OF THEREOF.

X ALL WORK O.O.D

Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11578
Phone (516) 478-4326
Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

2446

ADVISOR
PETER RODNEY

20

TRQ NO
1706

INVOICE DATE
10/28/11

INVOICE NO
ASCS15619

LABOR RATE

LICENSE NO

MILEAGE

2,630

COLOR

LIGHTNING S

STOCK NO

YEAR, MAKE, MODEL

09/ASTON MARTIN/DBS/DBS

DELIVERY DATE

01/17/09

DELIVERY MILES

509

VEHICLE ID NO

SCFAB06D49GE00855

SELLER'S DEALER NO

AM OF LI

PRODUCTION DATE

R.T.E. NO

P.O. NO

R.O. DATE

10/21/11

COMMENTS

MO: 2760

JOB# 1 CHARGES

LABOR

J# 1 00ASZ

SERVICE

HOURS: 10.00 TECH(S):08

1550.00

CUSTOMER REQUESTS THE 2 YEAR ANNUAL SERVICE
TWO YEARS SERVICE WAS PERFORMED. SERVICE HANDBOOK WAS
FILLED OUT AND STAMPED.

PARTS

QTY

FP-NUMBER

DESCRIPTION

UNIT PRICE

1

PK2YRD89

2 YR SERVICE DB9

22.37

1

4G43-04-10205

DRAIN PLUG

3.44

2

4G43-27-10245

COPPER WASHER

2.62

1

4G43-27-10491

O-RING 2.62

27.19

1

700781

CAS SUPER DOT 4

4.99

2

08180

BRAKE CLEANER

45.23

1

4G43-17528-CA

WIPER

39.80

1

9G43-178437-AA

WIPER

59.95

2

3JM-20972-3

ANTIFREEZE

44.34

1

AG43-6714-AA

OIL FILTER

101.14

2

4G43-9601-AB

AIR CLEANER

91.58

1

4G43-132E1-AA-PK

FILTER-POLLEN

11.20

13

OW-40

SYNTHETIC OIL

2.59

2

DSTL

DISTILLED WATER

4.53

1

W/A

WASHER FLUID

62.26

5

6G33-75106-AA/S

OIL-MAN TRANS 1LTR

1.22

4

1R12-36-10555

VALVE DUST CAP

1083.66

TOTAL - PARTS

1083.66

SUBLET

PO#

19608

VEND

2224

INV DATE

10/28/11 PICKUP AND DELIVER

TOTAL - SUBLET

INTERNAL

0.00

G.O.G. & SUPPLIES

1.0 GAS

@ 20.000 /UNIT

TOTAL - GOG

20.00

20.00

MISC

CODE

DESCRIPTION

CONTROL NO

LD2 10% LABOR DISCOUNT

PD3 15% PARTS DISCOUNT

TOTAL - MISC

155.00

-162.55

-317.55

JOB# 1 TOTALS

LABOR

1550.00

PARTS

1083.66

G.O.G.

20.00

MISC

-317.55

JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL

2336.11

JOB# 2 CHARGES

LABOR

J# 2 00ASX

EXTENDED SERVICE

HOURS: 0.00 TECH(S):08

0.00

EXTENDED SERVICE CONTRACT OFFER

CUSTOMER REQUESTS THE 2 YEAR ESC

ESC OFFER

X

ALL WORK C.O.D.

Thank You FOR BRINGING
YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK
PERFORMED AND RECEIPT OF COPY OF THEREOF.

N.Y.S. Repair Shop Registration No.
R-7099622

Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050

Phone (516) 478-4328

Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11576

Phone (516) 478-4326

Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

INVOICE NO. 2446	BUYER PETER RODNEY	TAG NO. 20 1706	INVOICE DATE 10/28/11	INVOICE NO. ASC515619
LABOR RATE	LICENSE NO.	MILEAGE 2,630	COLOR LIGHTNING S	STOCK NO.
YEAR / MAKE / MODEL 09 / ASTON MARTIN / DBS / DBS	DELIVERY DATE 01/17/09	DELIVERY MILES 509	SELLING DEALER NO. AM OF LI	PRODUCTION DATE
VEHICLE I.D. NO. SCFAB06D49GE00855	P.O. NO.	P.O. DATE 10/21/11		
COMMENTS				

MO: 2760

CUSTOMER APPROVED THE ESC, PERFORMED 140 POINT INSPECTION. CAR MEETS ESC CRITERIA.

SUBLET PO# 19605 VEND INV# 15619 INV. DATE 10/27/11 DESCRIPTION 2 YEAR ESC E00855 6500.00
TOTAL - SUBLET 6500.00

JOB# 2 TOTALS- SUBLET 6500.00

JOB# 2 JOURNAL PREFIX ASCS JOB# 2 TOTAL 6500.00

JOB# 3 CHARGES-

LABOR JOB# 3 51ASZ BODY ELECTRICAL HOURS: TECH(S):08 0.00
CUSTOMER FEELS HE HAS TO BE RIGHT ON TOP OF THE DOOR FOR THE REMOTES TO UNLOCK THE CAR. CHECK THE RANGE OF OPERATION. CHECKED RANGE OF REMOTE AND FOUND TO BE OPERATING AS DESIGNED. TESTED REMOTE FROM RIGHT NEXT TO VEHICLE AND FOUND TO BE OKAY. MOVED 5 FEET AWAY AND FOUND TO BE OPERATING OKAY. MOVED 10 FEET AWAY AND FOUND TO BE OPERATING OKAY. TRIED AGAIN AT 15 FEET FOUND TO BE OKAY. TEST A KNOWN GOOD VEHICLE AND FOUND THAT THE VEHICLE PRODUCED THE SAME RESULTS.

JOB# 3 TOTALS- JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-

LABOR JOB# 4 10ASZ DRIVEABILITY HOURS: TECH(S):08 0.00
CUSTOMER STATES THE STEERING WHEEL SHAKES AT 60-70 MPH AT 70 MPH IT STOPS VIBRATING. RECOMMEND TO REPLACE BOTH FRONT WHEELS AND TIRES. TESTED AND FOUND THAT THE TWO FRONT RIMS ARE BENT. CUSTOMER WAS ADVISED.

JOB# 4 TOTALS- JOB# 4 JOURNAL PREFIX ASCS JOB# 4 TOTAL 0.00

JOB# 5 CHARGES-

LABOR JOB# 5 60ASZ08 CONSOLE HOURS: TECH(S):08 0.00
CUSTOMER STATES THE ALUMINUM RING AROUND THE SHIFTER BOOT IS STARTING TO PIT. CHECKED OVER THE BASE RING ON THE SHIFTER BOOT. WAS UNABLE TO FIND ANY SIGNS OF PITTING. FOUND SEVERAL DIRT MARKS THAT WAS CLEANED AND A CHIP UNDERNEATH THE TRUNK RELEASE SWITCH.

JOB# 5 TOTALS- JOB# 5 JOURNAL PREFIX ASCS JOB# 5 TOTAL 0.00

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

ALL PARTS ARE NEW OR FACTORY REBUILT, PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY.

PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES: A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK PERFORMED AND RECEIPT OF COPY OF THEREOF.

X ALL WORK C.O.D.

Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11576
Phone (516) 478-4326
Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

CUSTOMER NO. 2446	ADVISOR PETER RODNEY	TRAQ NO. 20 1706	INVOICE DATE 10/28/11	INVOICE NO. ASCS15619
	LABOR RATE	LICENSE NO.	MILEAGE 2,630	COLOR LIGHTNING S
	YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS		DELIVERY DATE 01/17/09	STOCK NO.
	VEHICLE I.D. NO. S C F A B 0 6 D 4 9 G E 0 0 8 5 5		SELLING DEALER NO. AM OF LI	DELIVERY MILES 509
	TTT NO.	P.O. NO.	R.O. DATE 10/21/11	PRODUCTION DATE
COMMENTS				MO: 2760

TOTALS:

*
* ☐ CASH ☐ CHECK CK NO. [] *
* ☐ VISA ☐ MASTERCARD ☐ DISCOVER *
* ☐ AMER XPRESS ☐ OTHER ☐ CHARGE *

TOTAL LABOR.... 1550.00
TOTAL PARTS.... 1083.66
TOTAL SUBLET.... 6500.00
TOTAL G.O.G.... 20.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC -317.55
TOTAL TAX..... 774.41
TOTAL INVOICE \$ 9610.52

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

ALL PARTS ARE NEW OR FACTORY REBUILT, PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY.

PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES. A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR _____.

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK PERFORMED AND RECEIPT OF COPY OF THEREOF.

X
ALL WORK GOOD

Miller Motorcars Aston Martin Long Island



ASTON MARTIN

Service Location

85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11576
Phone (516) 478-4326
Fax (516) 478-4327



ASTON MARTIN

CELL: 856-266-6727

CUSTOMER NO 2446	ADVISED PETER RODNEY	TAXES 20 1943	INVOICE DATE 10/27/10	INVOICE NO ASCS14757
LABOR RATE	LICENSE NO	MILEAGE 2,109	COLOR LIGHTNING S	STOCK NO 2072
YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS	DELIVERY DATE 01/17/09	DELIVERY MILES 509	SELLING DEALER NO AM OF LI	PRODUCTION DATE
VEHICLE ID NO SCFAB06D49GE00855	DATE 10/20/10			
COMMENTS				

MO: 2115

JOB# 1 CHARGES

LABOR
J# 1 00AS7 SERVICE HOURS: 7.00 TECH(S):07 1085.00
CUSTOMER REQUESTS TO PERFORM THE 1 YEAR SERVICE
PERFORMED 1 YEAR SERVICE AS REQUESTED
PERFORMED 1 YEAR SERVICE AS PER MAINTANANCE TABLE

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
	1	2032	LITHIUM BATTERY	4.95	4.95
	1	PK1VRDB9	1YR SERVICE DB9	****	****
	1	4G43-04-10205	DRAIN PLUG	19.75	19.75
	1	700781	CAS SUPER DOT 4	24.48	24.48
	2	08180	BRAKE CLEANER	4.99	9.98
	1	4G43-17528-CA	WIPER	42.90	42.90
	1	9G43-17B437-AA	WIPER	38.89	38.89
	1	4G43-44-10818	OIL FILTER	43.46	43.46
	13	0W-40	SYNTHETIC OIL	10.95	142.35
	1	W/W	WASHER FLUID	4.53	4.53
TOTAL - PARTS				331.29	

JOB# 1 TOTALS

LABOR 1085.00
PARTS 331.29

JOB# 1 JOURNAL PREFIX ASCS JOB# 1 TOTAL 1416.29

JOB# 2 CHARGES

LABOR
J# 2 61ASZ20 EXT MIRROR HOURS: 0.35 TECH(S):01 07 WARRANTY
CUSTOMER STATES THE DRIVERS SIDE MIRROR VIBRATES AT 50-60
MPH. PASSENGER SIDE DOES NOT.
FOUND MIRROR BASE LOOSE AND MIRROR DAMPENING TABS WORN
WHICH CAUSES MIRROR TO VIBRATE AT SPEEDS MENTIONED ABOVE.
REPLACED MIRROR BASE AND MIRROR GLASS TO CORRECT

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
	1	8D33-17683-DC	MIRROR ASSY-LH		
	1	6G43-37-10127	MIRROR GLASS-LH FL		
TOTAL - PARTS				0.00	

JOB# 2 TOTALS

JOB# 2 JOURNAL PREFIX ASCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR
J# 3 60ASZ04 DOOR HANDLE HOURS: TECH(S):07 20 INTERNAL
CUSTOMER STATES WHEN OPENING THE DOOR FROM THE INSIDE THE
DOOR POPS OPEN AS IF UNDER TENSION. SEE LIST ON BACK OF P.O.
DOOR STRIKER REQUIRES ADJUSTMENT
ADJUSTED DOOR STRIKER AS BEST AS POSSIBLE. STILL SOME
TENSION BUT NO MORE ADJUSTMENT IS AVAILABLE OR THE DOOR WILL
NOT CLOSE PROPERLY OR LINE UP WITH THE BODY OF THE CAR.

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. ALL PARTS ARE NEW OR FACTORY REBUILT. PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY. PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES. A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING
YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK
PERFORMED AND RECEIPT OF COPY OF THEREOF

X
ALL WORK C.O.D



ASTON MARTIN

Miller Motorcars Aston Martin Long Island

Service Location

85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location

1060 Northern Blvd. - Roslyn, NY 11578
Phone (516) 478-4326
Fax (516) 478-4327



ASTON MARTIN

DISTANCE NO 2446		ADVISOR PETER RODNEY		20	1943	INVOICE DATE 10/27/10	INVOICE NO ASCS14757
LABOR RATE		LICENSE NO		MILEAGE 2,109		COLOR LIGHTNING S	STOCK NO 2072
YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS						DELIVERY DATE 01/17/09	DELIVERY MILES 509
VEHICLE I.D. NO S C F A B 0 6 D 4 9 G E 0 0 8 5 5						SELLING DEALER NO AM OF LI	PRODUCTION DATE
P.T. E. NO		P.O. NO		R.G. DATE 10/20/10			
COMMENTS							

CELL: 856-266-6727

MO: 2115

JOB# 3 TOTALS
JOB# 4 CHARGES
JOB# 3 JOURNAL PREFIX ASCS JOB# 3 TOTAL 0.00

LABOR
JOB# 4 51ASZ
BODY ELECTRICAL HOURS: TECH(S):07 20
CUSTOMER STATES THE IPOD DOES NOT CHARGE REQUESTING A
SOFTWARE UPDATE IF AVAILABLE.
LATEST IPODS WILL NOT BE ABLE TO CHARGE ON THE 09 DBS
APPLE HAS CHANGED THE IPOD TO A 5 VOLT SYSTEM

JOB# 4 TOTALS
JOB# 5 CHARGES
JOB# 4 JOURNAL PREFIX ASCS JOB# 4 TOTAL 0.00

LABOR
JOB# 5 70ASZ
SUBLET HOURS: TECH(S):07 20
CUSTOMER REQUESTS A CLEAR BRA INSTALLED ON THE BUMPER
HOOD AND CARBON FIBER. CHECK DAMAGE ON FRONT SPOILER.
FRONT LOWER SPOILER IS SCRATCHED
TOUCHED UP FRONT SPOILER HAS BODY SHOP LOOK AT THE SPOILER
AND AGREE NOT TO REPAINT. INSTALLED FRONT PAINT PROTECTION
PACKAGE INCLUDING LOWER CARBON FIBER PANELS.

SUBLET PO# VENDOR INV# INV DATE DESCRIPTION
19151 2010-807 10/26/10 FT PACKAGE PROTEC E00855
TOTAL - SUBLET 1850.00

JOB# 5 TOTALS
SUBLET 1850.00

JOB# 6 CHARGES
JOB# 5 JOURNAL PREFIX ASCS JOB# 5 TOTAL 1850.00

LABOR
JOB# 6 00ASX
EXTENDED SERVICE HOURS: TECH(S):07
EXTENDED SERVICE CONTRACT OFFER
PERFORM 140 POINT INSPECTION
ESC OFFER
CUSTOMER HAS DECLINED EXTENDED COVERAGE AT THIS TIME

JOB# 6 TOTALS
JOB# 6 JOURNAL PREFIX ASCS JOB# 6 TOTAL 0.00

LABOR
JOB# 7 57ASZ
CAMPAIGN HOURS: 0.20 TECH(S):07
PERFORM REFLASH OF POWERTRAIN CONTROL MODULE.
SA-03-0175 .2
CONNECTED AMDS TO REFLASH POWERTRAIN CONTROL MODULE

ANY WARRANTIES ON THE PRODUCTS
SOLD HEREBY ARE THOSE MADE BY THE
MANUFACTURERS. THE SELLER HEREBY
EXPRESSLY DISCLAIMS ALL WARRANTIES.
EITHER EXPRESS OR IMPLIED, INCLUDING
ANY IMPLIED WARRANTY OF MERCHANT-
ABILITY OR FITNESS FOR A PARTICULAR
PURPOSE, AND NEITHER ASSUMES NOR
AUTHORIZES ANY OTHER PERSON TO
ASSUME FOR IT ANY LIABILITY IN CONNEC-
TION WITH THE SALE OF SAID PRODUCTS.

ALL PARTS ARE NEW OR FACTORY
REBUILT. PARTS MARKED WITH AN X PRE-
CEDING THE PART NUMBER ARE NOT SUP-
PLIED BY ASTON MARTIN AND MAY HAVE
BEEN IMPORTED DIRECTLY FROM EUROPE
OR MANUFACTURED IN THE U.S.A. THEY
ARE IN MOST CASES ORIGINAL PARTS AND
ARE OF THE FINEST QUALITY.

PARTS AND LABOR ARE SUBJECT TO
SEPARATE WARRANTIES. A COPY OF
PARTS WARRANTY MAY BE OBTAINED
FROM THE CASHIER. THE WARRANTY ON
LABOR IS 12 MONTHS OR 12,000 MILES,
WHICHEVER OCCURS FIRST EXCEPT
ADJUSTMENTS THAT ARE WARRANTED
FOR

N.Y.S. Repair Shop Registration No.
R-7099822

Thank You FOR BRINGING
YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK
PERFORMED AND RECEIPT OF COPY OF THEREOF

X
ALL WORK C.O.D.

Miller Motorcars Aston Martin Long Island



Service Location
85 Channel Dr. - Port Washington 11050
Phone (516) 478-4328
Fax (516) 478-4329

Sales Location
1060 Northern Blvd. - Roslyn, NY 11576
Phone (516) 478-4328
Fax (516) 478-4327



CELL: 856-266-6727

2446

ADVISOR PETER RODNEY	TAG NO. 20 1943	INVOICE DATE 10/27/10	INVOICE NO. ASCS14757
LABOR RATE	LICENSE NO.	MILEAGE 2,109	COLOR LIGHTNING S
YEAR / MAKE / MODEL 09/ASTON MARTIN/DBS/DBS		DELIVERY DATE 01/17/09	DELIVERY MILES 509
VEHICLE ID. NO. S C F A B 0 6 D 4 9 G E 0 0 8 5 5		SELLING DEALER NO. AM OF LI	PRODUCTION DATE
P.T.E. NO.		P.O. NO.	R.C. DATE 10/20/10
COMMENTS			

MO: 2115

JOB# 7 TOTALS

JOB# 7 JOURNAL PREFIX ASCS JOB# 7 TOTAL 0.00

TOTALS

* [] CASH [] CHECK CK NO. [] *
* [] VISA [] MASTERCARD [] DISCOVER *
* [] AMER XPRESS [] OTHER [] CHARGE *

TOTAL LABOR.... 1085.00
TOTAL PARTS.... 331.29
TOTAL SUBLET.... 1850.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC 0.00
TOTAL TAX..... 281.72

TOTAL INVOICE \$ 3548.01

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURERS. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

ALL PARTS ARE NEW OR FACTORY REBUILT, PARTS MARKED WITH AN X PRECEDING THE PART NUMBER ARE NOT SUPPLIED BY ASTON MARTIN AND MAY HAVE BEEN IMPORTED DIRECTLY FROM EUROPE OR MANUFACTURED IN THE U.S.A. THEY ARE IN MOST CASES ORIGINAL PARTS AND ARE OF THE FINEST QUALITY.

PARTS AND LABOR ARE SUBJECT TO SEPARATE WARRANTIES. A COPY OF PARTS WARRANTY MAY BE OBTAINED FROM THE CASHIER. THE WARRANTY ON LABOR IS 12 MONTHS OR 12,000 MILES, WHICHEVER OCCURS FIRST EXCEPT ADJUSTMENTS THAT ARE WARRANTED FOR _____.

N.Y.S. Repair Shop Registration No.
R-7099622

Thank You FOR BRINGING YOUR CAR TO US FOR SERVICE.

I ACKNOWLEDGE AND PRODUCT EXTRA WORK PERFORMED AND RECEIPT OF COPY OF THEREOF.

X
ALL WORK C.O.D.



ASTON MARTIN

DBS VEHICLE MAINTENANCE SHEET

Always use body interior protection and the correct grades of lubricants and fluids. Tick the 'C' box when the check is complete and tick the 'A' box if corrective action was necessary. THOROUGHLY CLEAN THE VEHICLE AND WORKING ZONE.

Owner: [REDACTED]

Date: 10/22/10

Vehicle Reg. No.: SCFA336 60496

Key No.:

Speedo (km/mi): 2109

Derivative: DBS Coupe / 1st service

Dealers Job/Invoice No.: 14757

VIN: EC0855

10,000 mi / 16,000 km / 12 months	20,000 mi / 32,000 km / 24 months			
Pre-Maintenance				
☒	☒	Fit vehicle protection kit and wind covers	☒	☒
☒	☒	Check C-pillar status	☒	☒
Fluid, Filters and Leaks Check				
☒	☒	Brake engine oil	☒	☒
☒	☒	Renew engine oil filter	☒	☒
☒	☒	Check for engine oil leaks	☒	☒
☒	☒	Renew the air cleaner element	☒	☒
☒	☒	Check transmission and final drive oil levels, top up if necessary	☒	☒
Every 6 yrs / 50,000 mi / 80,000 km	Every 10 yrs / 100,000 mi / 160,000 km	Check manual transaxle oil level, top up if necessary	☒	☒
Every 4 yrs or 40,000 mi (64,000 km)		Renew manual transaxle oil and clean filter	☒	☒
☒	☒	Check/replace engine coolant	☒	☒
☒	☒	Check cooling and heating system for leaks	☒	☒
Every 5 yrs or 100,000 mi (160,000 km)		Renew engine coolant - ensure concentration 50/50	☒	☒
☒	☒	Check fuel hoses, pipes and unions for leaks, security and condition	☒	☒
Every 12 months		Renew brake/clutch fluid (ensure correct specifications)	☒	☒
☒	☒	Check/top up brake/clutch fluid reservoir	☒	☒
☒	☒	Check/top up power steering reservoir	☒	☒
☒	☒	Check power steering system for leaks, security and condition	☒	☒
☒	☒	Check brake hoses, pipes and unions for leaks, security and condition	☒	☒
☒	☒	Check suspension dampers for leaks	☒	☒
☒	☒	Top up windscreen/headlamp washer reservoir	☒	☒
☒	☒	Check exhaust system for leaks	☒	☒
☒	☒	Check exhaust bypass valve operation 800/3000 rpm	☒	☒
☒	☒	Check air conditioning system for leaks (U/V visual)	☒	☒
☒	☒	Renew pollen filter	☒	☒

10,000 mi / 16,000 km / 12 months	20,000 mi / 32,000 km / 24 months			
Mechanical function Check				
☒	☒	Lubricate all door lock hinges/joints	☒	☒
☒	☒	Lubricate bonnet secondary latch	☒	☒
☒	☒	Check security of bonnet catch and check that the bonnet secondary catch moves freely over its whole travel and returns smoothly under spring pressure	☒	☒
☒	☒	Check/adjust polyvex drive belt tension, renew if necessary	☒	☒
☒	☒	Adjust handbrake cables if necessary	☒	☒
☒	☒	Check handbrake security	☒	☒
☒	☒	Check condition of handbrake pads	☒	☒
☒	☒	Inspect brake pad wear and condition of discs and callipers. At 60% down worn replace brake pads and pad wear warning leads. Update Owner's Guide if pads changed. At every 1" pad change clean, dry and weight discs and replace if necessary	☒	☒
☒	☒	Check front brake disc shields for fatigue cracks around braces and for clearance to discs	☒	☒
☒	☒	Check and renew wiper blade inserts if necessary	☒	☒
☒	☒	Renew wiper blades	☒	☒
☒	☒	Inspect cooling pack radiator/condenser and transmission cooler for debris and clean out if necessary	☒	☒
☒	☒	Check condition and operation of all seat belts and buckles	☒	☒
☒	☒	Check security of exhaust system mountings and heat shields	☒	☒
☒	☒	Check security and condition of cooling system hoses	☒	☒
☒	☒	Check security and condition of air conditioning hoses	☒	☒
☒	☒	Check security and condition of suspension ball joints, gaiters, bushes and fixings	☒	☒
☒	☒	Check tightness of drive shaft bolts	☒	☒
☒	☒	Check rear view mirror for security and function	☒	☒
☒	☒	Check the condition of underbody protection/wheel arch liners	☒	☒
Every 4 years or 40,000 mi (64,000 km)		Clean throttle butterflies	☒	☒

Note: To ensure maximum customer satisfaction it is recommended that a road test is carried out prior to commencement of maintenance services, as well as afterwards. Regardless of low service mileage, time intervals should always be actioned to ensure optimum vehicle condition and customer satisfaction

DBS VEHICLE MAINTENANCE SHEET

10,000 mls
16,000 km
12 months

20,000 mls
32,000 km
24 months

Electrical Function Check

Every 70,000 mls (112,000 km)			C	A
X	X	Renew spark plugs	✓	✓
X	X	Check and report battery voltage	✓	✓
X	X	Check and service the battery connection if necessary	✓	✓
X	X	Check and if necessary adjust headlamp alignment	✓	✓
X	X	Check operation of all lights	✓	✓
X	X	Check operation of all warning indicators	✓	✓
X	X	Check audible warnings including security system	✓	✓
X	X	Check operation of the horns	✓	✓
X	X	Check operation of the windscreen wipers	✓	✓
X	X	Check operation of the windscreen/headlight washers/jets	✓	✓
X	X	Check rear view mirrors for security and function/washers	✓	✓
X	X	Check fold back mirrors if fitted	✓	✓
X	X	Check electric window operation	✓	✓
X	X	Check the battery disconnect/connect switch	✓	✓
X	X	Check the service indicator and reset	✓	✓
X	X	Replace remote key fob battery	✓	✓

Anti Corrosion Check

			C	A
X	X	Check body panels and under body for corrosion starting from the inside out (excluding stone chips)	✓	✓

10,000 mls
16,000 km
12 months

20,000 mls
32,000 km
24 months

Wheels and Tyres Check

			C	A
X	X	Check for correct tyre size, type and orientation	✓	✓
X	X	Check and report tyre tread depth	✓	✓
X	X	Check tyres for uneven/excessive wear or damage	✓	✓
X	X	Check/adjust tyre pressures	✓	✓
X	X	Cheque torque of road wheel nuts	✓	✓
X	X	Check road wheel rims for inner and outer damage and report	✓	✓
X	X	Check colour coded Tyre Pressure Monitor System valve caps are on correct wheels (if applicable)	✓	✓
X	X	Check operation of tyre pressure sensors	✓	✓
X	X	Check date of tyre inflation kit	✓	✓


Final Checks

			C	A
X	X	Degrease windscreen	✓	✓
X	X	Carry out road test	✓	✓
X	X	Check ABS and Traction Control operation	✓	✓
X	X	Check operation of all seat belts and buckles	✓	✓
X	X	Check that fuel filler bowl drain is clear	✓	✓
X	X	Check adaptive damping operation	✓	✓

Dealer Stamp

Aston Martin Long Island
85 Channel Dr.
Port Washington, NY 11050

Record fuel level on arrival at Dealership
Note: Always fill fuel tank before returning



Open Circuit
Battery Voltage

12.21v

To remove surface charge:
- Key in ignition, switch ON
- Headlamps ON 4 mins
- Headlamps OFF 2 mins
- Key out of ignition (OFF)
- Test battery voltage

Tyre Wear Report

	Outer	Centre	Inner	Outer	Centre	Inner
CW Rotation	Across Tyre			Across Tyre		
Valve	LHF mm			RHF mm		
90°	65	6	6	6.5	6	6
180°	1	1	1	1	1	1
270°	1	1	1	1	1	1
Tyre pressure	LHR mm			RHR mm		
Valve	6	55	55	6	55	55
90°	1	1	1	1	1	1
180°	1	1	1	1	1	1
270°	1	1	1	1	1	1
Tyre pressure						

Regardless of low service mileage, time intervals should always be actioned to ensure optimum vehicle condition and customer satisfaction

PROPER CAR REPAIR AND YOUR SATISFACTION ARE BOTH IMPORTANT TO US. THE WORK WE PERFORMED IS IN ACCORDANCE WITH THE MANUFACTURER'S SPECIFICATION, GOVERNMENT REGULATIONS AND OUR PRIDE OF WORKMANSHIP.
PREVENTATIVE MAINTENANCE IS THE LEAST EXPENSIVE COST OF OPERATING YOUR CAR. LET US SERVICE YOUR CAR REGULARLY TO PREVENT AS MANY MECHANICAL FAILURES, AS POSSIBLE.

Thank you for giving The Collection Service Department this opportunity to service your automotive needs. If you have any questions about your bill or are not completely satisfied with the repairs as performed, please contact your service advisor or our customer relations representative.

LIMITED WARRANTY: The only warranties applying to the part(s) installed in accordance with this estimate are those that may be offered by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of products or service sold under the terms of this estimate. Refer to the back of your customer copy for individual parts and labor guarantees. Seller does not guarantee that the work performed in accordance with this estimate will correct any problem specified on the description of the complaint.

CUSTOMER HEREBY ACKNOWLEDGES RECEIPT OF ABOVE MENTIONED VEHICLE, AND RECEIPT OF INVOICE COPY HEREOF.

CUSTOMER SIGNATURE

LABOR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

MISC. CHARGES

TOTAL CHARGES

DEDUCTIONS

SALES TAX

PLEASE PAY THIS AMOUNT

CUSTOMER COPY

924829

INVOICE

THE COLLECTION

200 Bird Road, Coral Gables, FL 33146 Tel: (305) 444-1111
thecollection.com

PAGE 2

MV - 00154

MVR - 00058

SERVICE ADVISOR: 610 STEVEN ASTON MCALOON

SILVER 09 ASTON MARTIN DBS SCFAB06D49GE00855 9828/9831 T10594

01JAN09 IS 16:00 09OCT21 0.00 CASH 11OCT21

OPTIONS: DLR:5708

11:57 08OCT21 17:22 11OCT21

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER							69.95

PROPER CAR REPAIR AND YOUR SATISFACTION ARE BOTH IMPORTANT TO US. THE WORK WE PERFORMED IS IN ACCORDANCE WITH THE MANUFACTURER'S SPECIFICATION, GOVERNMENT REGULATIONS AND OUR PRIDE OF WORKMANSHIP.
PREVENTATIVE MAINTENANCE IS THE LEAST EXPENSIVE COST OF OPERATING YOUR CAR. LET US SERVICE YOUR CAR REGULARLY TO PREVENT AS MANY MECHANICAL FAILURES, AS POSSIBLE.

Thank you for giving The Collection Service Department this opportunity to service your automotive needs. If you have any questions about your bill or are not completely satisfied with the repairs as performed, please contact your service advisor or our customer relations representative.

LIMITED WARRANTY: The only warranties applying to the part(s) installed in accordance with this estimate are those that may be offered by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of products or service sold under the terms of this estimate. Refer to the back of your customer copy for individual parts and labor guarantees. Seller does not guarantee that the work performed in accordance with this estimate will correct any problem specified on the description of the complaint.

CUSTOMER HEREBY ACKNOWLEDGES RECEIPT OF ABOVE MENTIONED VEHICLE, AND RECEIPT OF INVOICE COPY HEREOF.

CUSTOMER SIGNATURE

LABOR AMOUNT

2278.92

PARTS AMOUNT

656.91

GAS, OIL, LUBE

0.00

SUBLET AMOUNT

0.00

MISC. CHARGES

69.95

TOTAL CHARGES

3005.78

DEDUCTIONS

0.00

SALES TAX

210.34

PLEASE PAY THIS AMOUNT

CUSTOMER COPY

10/12/21, 12:14 PM

Gmail - Your Payment Receipt



Your Payment Receipt

cashiers@thecollection.com <cashiers@thecollection.com>
To: T81OFFICE@gmail.com

Tue, Oct 12, 2021 at 12:13 PM



THE COLLECTION
200 Bird Road
Coral Gables Florida 33146
3054445555

Customer Information:

Transaction Information:

Sale

Internet Transaction

Date: 10/12/2021 12:13:38

Amount: \$3216.12

Card Number: *****7883

Merchant ID: 12723443

Auth. Code: 743261

Processed As: VISA



Tue, Oct 12, 2021 at 12:13 PM



THE COLLECTION
200 Bird Road
Coral Gables Florida 33146
3054445555

Transaction Information:

Sale
Internet Transaction
Date: 10/12/2021 12:13:38
Amount: \$3216.12
Card Number: *****7883
Merchant ID: 12723443
Auth. Code: 743261
Processed As: VISA
Reference No.: 1942132888
Trace No.: N/A
Device ID.: 5312
Invoice No.: 924829_CJ-S_2021-10-08_1
Response Msg.: Approved
Entry Method: Manual
P.O. Number:

Thank you for allowing us the privilege of helping you today.

THE COLLECTION



PAYMENTS

Payment Type	Last Four	Message	Amount	Donations	Surcharge	Reference Number
CREDITCARD	7883	Approved	\$ 3,216.12	\$ 0.00	\$ 0.00	1942132888
Authorization Code 743261						





924829

INVOICE

THE COLLECTION®

200 Bird Road, Coral Gables, FL 33146 Tel: (305) 444-1111
thecollection.com

PAGE 1

MV - 00154

MVR - 00056

SERVICE ADVISOR: 610 STEVEN ASTON MCALOON

SILVER	09	ASTON MARTIN DBS	SCFAB06D49GE00855		9828/9831	T10594
--------	----	------------------	-------------------	--	-----------	--------

01JAN09 IS			16:00 09OCT21		0.00	CASH	11OCT21
------------	--	--	---------------	--	------	------	---------

OPTIONS: DLR:5708

11:57 08OCT21 17:22 11OCT21

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUSTOMER REQUESTS TO PROGRAM THE TWO NEW KEYS IN THE VEHICLE

06 PROGRAM SUPPLIED KEYS

8537 CAM

239.99 239.99

9828 REQUEST TO PROGRAM KEYS 1.00 PROGRAM SUPPLIED KEYS AS REQUESTED...

B** AM CUST REQUESTS TO PERFORM A TWO YEAR SERVICE

AM2YEAR AM CUST REQUESTS TO PERFORM A TWO YEAR

SERVICE

8537CAMMT

1799.93 1799.93

1 AG43-6714-AA OIL FILTER(SINGLE) 46.47 46.47 46.47

1 4G43-04-10205 PLUG-OIL PAN DRAIN 23.73 23.73 23.73

1 1R12-08-10317 O RING 2.92 2.92 2.92

12 AMOBIL1 15W50 MOBIL1 OIL 10.45 10.45 125.40

1 4G43-9601-AB-PK FILTER AIR CLEANER BOX OF 2 177.33 177.33 177.33

1 4G43-13ZE1-AA-PK FILTER-POLLEN BOX OF 2 94.76 94.76 94.76

3 TCC6330 R134 REFRIG 17.33 17.33 51.99

3 4790X SHELL TRANSAXLE OIL GEA 23.90 23.90 71.70

2 6G33-FA0115-AB-SCREW M6X19 TORX HD 0.46 0.46 0.92

9831 SERVICE INTERVAL 7.50 PERFORM TWO YEAR SERVICES AND CHECKS...

C** PERFORM 2ND YEAR BRAKE FLUSH

0102530 PERFORM 2ND YEAR BRAKE FLUSH

8537 CAM

239.00 239.00

1 35401 DOT BRAKE FLUID 32OZ 61.69 61.69 61.69

9828 REQUESTED BRAKE FLUID SERVICE 1.00 PERFORM REQUESTED BRAKE FLUID SERVICES...

D** ASTON MARTIN COURTESY VEHICLE MULTI POINT INSPECTION

MULTIAM ASTON MARTIN COURTESY VEHICLE MULTI POINT

INSPECTION

8537IPOST

(N/C)

9828 0.00 PERFORM ELECTRONIC DOCUMENTATION CHECKLIST SAFETY CHECKS

PROPER CAR REPAIR AND YOUR SATISFACTION ARE BOTH IMPORTANT TO US. THE WORK WE PERFORMED IS IN ACCORDANCE WITH THE MANUFACTURER'S SPECIFICATION, GOVERNMENT REGULATIONS AND OUR PRIDE OF WORKMANSHIP. PREVENTATIVE MAINTENANCE IS THE LEAST EXPENSIVE COST OF OPERATING YOUR CAR. LET US SERVICE YOUR CAR REGULARLY TO PREVENT AS MANY MECHANICAL FAILURES, AS POSSIBLE.

Thank you for giving The Collection Service Department this opportunity to service your automotive needs. If you have any questions about your bill or are not completely satisfied with the repairs as performed, please contact your service advisor or our customer relations representative.

LIMITED WARRANTY: The only warranties applying to the parts installed in accordance with this estimate are those that may be offered by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of products or service sold under the terms of this estimate. Refer to the back of your customer copy for individual parts and labor guarantees. Sales does not guarantee that the work performed in accordance with this estimate will correct any problem specified on the description of the complaint.

CUSTOMER HEREBY ACKNOWLEDGES RECEIPT OF ABOVE MENTIONED VEHICLE, AND RECEIPT OF INVOICE COPY HEREOF.

CUSTOMER SIGNATURE

LABOR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

MISC. CHARGES

TOTAL CHARGES

DEDUCTIONS

SALES TAX

PLEASE PAY THIS AMOUNT

Copyright 2014 CCR Global, LLC. SERVICE INVOICE TYPE 1 - BDC - IMAGING

CUSTOMER COPY



924829

INVOICE

THE COLLECTION®

200 Bird Road, Coral Gables, FL 33146 Tel: (305) 444-1111
thecollection.com

PAGE 2

MV - 00154

MVR - 00056

SERVICE ADVISOR: 610 STEVEN ASTON MCALOON

SILVER	09	ASTON MARTIN DBS	SCFAB06D49GE00855		9828/9831	T10594
--------	----	------------------	-------------------	--	-----------	--------

01JAN09 IS			16:00 09OCT21		0.00	CASH	11OCT21
------------	--	--	---------------	--	------	------	---------

OPTIONS: DLR:5708

11:57 08OCT21 17:22 11OCT21

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER

69.95