

220S cab 1959
as of 1/17/2020

Battery		replaced 1/17/2020
Spark Plugs		
Ignition wires		
Ignition coil		
Starter	11-1 Starter	installed 10/19/16
Ignition system	123Merc6RV	installed 10/16/16
Brake master cylinder		
Brake fluid		replaced 3/28/16
Brake hoses		tightened 10/19/16
Brake drums		
Brake cylinders		replaced rear 3/28/16
Coolant		replaced 3/28/2016
Waterpump		
Thermostat		
Fuel hose		
Fuel filter		
Fuel pump	Electronic	installed 10/19/16
Carb adjustment		
Oil and filter		replaced 3/28/16
Air filter		
Transmission fluid		
Transmission seal		
Rear axle		
Lubricate fittings and hinges		
Fuel tank sending unit		
Pinion seal		
Steering box		
Muffler & exhaust		replaced 3/28/2016
Shocks		replaced 3/28/2016
Wheel alignment		
Tires		
Valves, guides, springs		replaced 3/28/16

INVOICE

B.L.Adams, LLC
 503 South Glenwood Trail
 Southern Pines, NC 28387
 www.bruceadams190sl.com
 "A 190 SL Restoration Company"

Date	Invoice No.
10/31/16	1233

Bill To

Terms
Due on receipt

Fahrgestell-Nr.
9500275

Serviced	Description	Amount
09/22/16	Diagnosis defective starter - 2 hrs	120.00
09/22/16	Featherlite Trailer	10,000.00
09/27/16	11-1 Starter & spacer ring/DHL Germany	325.00
10/06/16	Electronic Fuel Pump	235.78
10/16/16	123/Merc6RV Electronic Ignition/UPS	525.00
10/19/16	Install electronic fuel pump & wiring to switch - 5 hrs	300.00
10/19/16	Remove/install starter - test drive & eval running condition 5 hrs	300.00
10/19/16	Check for brake leaks: tighten brake lines @ brake cylinders - 2 hrs	120.00
10/20/16	Install 123, test drive & fuel	140.00

Accepting All Major Credit Cards	Total	\$12,065.78
----------------------------------	--------------	--------------------

*CODE N-NEW U-USED R-REBUILT

QTY	PART NO. OR DESCRIPTION	SALE
2	FRONT SHOCKS	250.00 500.00
2	REAR SHOCKS	175.00 350.00
2	REAR BRAKE WHEEL CYLIND	134.00 268.00
1	L BRAKE FLOOR	13.50
12	VALVE SPRINGS	4.50 54.00
6	INTAKE VALVES	65.00 390.00
6	EXHAUST VALVES	70.00 420.00
1	WATER VALVE DIVERTER	25.00
1	REAR MUFFLER	212.00
1	TRAIL ARM BUSHINGS KIT	125.00
1	COOLANT	23.50
1	OIL FILTER KIT	8.50
1	HEAD GASKET SET	154.00
1	VL GASKET SET	18.50

TOTAL PARTS ▶

2764.00

TIRE PRESSURE CHECK SERVICE COMPLETED
 TIRE PRESSURE: LF 32 RF 32 LR 32 RR 32
 DECLINED BY Initial REASON

SUBLET REPAIRS

MACHINE SHOP	1158.00
SHIPPING	50.00
MUFFLER SHOP	500.00
TOTAL SUBLET REPAIRS ▶	1708.00

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.

Since 1979

1295 Rollins Road

Since 1979

BURLINGAME, CA 94010-2416
 (650) 343-8858 Fax (650) 343-9261

EPA #CAL 000398238

BAR #ARD275257

Date 3.28.16
 Time Received 5:00 AM
 Written By RWE
 Cust. Order No.
 Promised Call AM
 Phone when ready Yes No
 Call Phone COLL @ AOL.COM
 Home Phone
 Work Phone 336 413 4748
 Other

Year 89 License No. 2205 Motor No. 11VER883 Color 6057
 Estimate Amount \$ 1100.00 Engine Size VIN Number
 Revised Estimate \$
 Revised Estimate \$

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE. SAVE DISCARD
 Authorized By INITIAL
 Authorized By INITIAL

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

REPAIR ORDER — LABOR INSTRUCTION

CHECK CAR OVER AS PER LIST FROM L.R. SPENCER
 R/R CYLINDER HEAD AND SEND OUT FOR VALVE JOB
 REPAIR ALL GUIDES + VALVES + SPRINGS, REPAIR ALL HARMED STAYS
 NEED COVERED WATER JACKETS AND MACHINE, REPAIR ROCKER ARM THREADS

R/R REAR BRAKE WHEEL CYLINDERS, BLEED BRAKES

REPLACE ALL FOUR SHOCKS
 REPAIR REAR TRAILING ARM BUSHINGS
 CHECK DIFF FOR LEAKS — CLEAN AND INSPECT
 SEND CAR TO MUFFLER SHOP FOR NEW EXHAUST SYSTEM
 CHECK ELECTRICAL SYSTEMS

WARRANTY ON PARTS & LABOR

3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST
 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST
 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST
 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST
 NOT GUARANTEED - NEED ADDITIONAL SERVICE(S)
 WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.

RECOMMENDED SERVICE:

1
 2
 3

If I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.
 Authorized By Phone

TOTAL LABOR ▶	2925.00
PARTS	2562.00
SUBLET REPAIRS	1708.00
OIL & GREASE	38.50
GAS	20.00
SALES TAX	230.58
HAZARDOUS WASTE DISPOSAL FEE	6.00
TOTAL AMOUNT ▶	7451.58

QTY.	SALE
7 QTS. OIL	5.25 36.75
LBS. GREASE	38.50
TOTAL OIL, GREASE	38.50

